

Source: Technos, 2007

LEGEND

- Magnetometer Survey Lines
- Seismic Refraction Survey Lines
- Interpreted Dike Locations
- Known Mapped Dikes
- Faults
- Magnetometer Survey Response

Progress Energy Carolinas

Shearon Harris Nuclear Power Plant
Units 2 and 3
Part 2, Final Safety Analysis Report

New Hill, North Carolina

Magnetometer Survey Results and Mapped Diabase Dikes

FIGURE 2.5.4-213

Rev. 0