NRC FORM 591M PART 1
(10-2003) 10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
Consultants in Cardiology, P.C. Farmington Hills, MI REPORT NUMBER(S) 2009-001	U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351

3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)	5. DATE(S) OF INSPECTION
030-33785	21-26635-01	August 18, 2009

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

☒ 1. Based on the inspection findings, no violations were identified.

☐ 2. Previous violation(s) closed.

☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

☐ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Deborah A. Piskura	Deborah A. Piskura	8/18/2009

NRC FORM 591M PART 3
(10-2003) 10 CFR 2.201

Docket File Information

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE	2. NRC/REGIONAL OFFICE
Consultants in Cardiology, P.C. REPORT NUMBER(S) 2009-001	**Region III** **2443 Warrenville Road, Suite 210** **Lisle, IL 60532**

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-33785	21-26635-01	Aug. 18, 2009

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
87130	03.01 – 03.08

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
02201	5	Abhinav Raina, M.D., RSO	248-865-9898

[X] Main Office Inspection — Next Inspection Date: Aug. 2014

[ ] Field Office

[ ] Temporary Job Site Inspection

PROGRAM SCOPE

This licensee was a small cardiac diagnostic office authorized to use licensed material permitted by Section 35.200 (limited to cardiovascular imaging procedures). The nuclear medicine department was staffed with 1 technologist who performed approximately 70-100 diagnostic cardiac procedures monthly. The licensee received unit doses from a licensed radiopharmacy. The licensee's consultant audited the radiation safety program on a quarterly basis.

This inspection consisted of interviews with licensee personnel, a review of selected records, tour of the nuclear medicine department, and independent measurements. The inspection included observations of dose calibrator QA checks, security of licensed material, package return surveys, and use of personnel monitoring.