NRC FORM 591M PART 1
(10-2003)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
US Dept of Homeland Security, Transportation Security Lab, Hughes Tech Center, Bldg 315 Atlantic City International Airport Atlantic City, NJ 08405 REPORT Nos 2009001	**U.S. Nuclear Regulatory Commission** **Region I, 475 Allendale Road** **King of Prussia, Pennsylvania 19406-1415**

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
03030808	29-13141-06	August 5, 2009

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

☐ 1. Based on the inspection findings, no violations were identified.

☒ 2. Previous violation(s) closed.

☐ 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

☐ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

☒ 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.

10 CFR 30.41 (c) requires, in part, that before transferring byproduct material to a specific licensee of the Commission or an Agreement State, the licensee transferring the material shall verify that the transferee's license authorizes the receipt of the type, form and quantity of byproduct material to be transferred. Contrary to the above, since February 2004, the licensee did not verify before transferring byproduct material to a specific licensee that the transferee was authorized to receive the byproduct material. The licensee agrees, effective as of August 5, 2009, to verify before transferring byproduct material, that the transferee is licensed to receive the byproduct material.

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE	Curtis J. Bell, Ph. D.		8/5/2009
NRC INSPECTOR	Todd J. Jackson, CHP		8/5/2009

SUNSI Review Completed By: /RA/ TJJ ☒ Public ☒ Non-Sensitive