ATTACHMENT I

STEAM GENERATOR INSPECTION PLAN

FOR THE CYCLE 3/4 REFUELING OUTAGE

POWER AUTHORITY OF THE STATE OF NEW YOTK

INDIAN POINT 3 NUCLEAR POWER PLANT

DOCKET NO. 50-286

FEBRUARY 26, 1982

8203030156 820226
PDR ADOCK 05000286
Q PDR

Notes:

1. Tubes outside boundary lines 1 and 2 will be inspected for denting (gauging program). All the tubes which did not pass the previous (Mid-Cycle 3) #700 probe inspection are boxed-in.
2. Slashes (/) indicate tubes to be inservice inspected per IP-3, TS § 4.9 (this includes approx. 45 peripheric: l tubes gauge inspected).
3. ▯ Indicate previously plugged tubes.

SERIES 44

INT-31



Notes:

1. Slashes (/) indicate tubes which will be inspected for denting (gauging program).
2. [E] Indicate previously plugged tubes.

SERIES

INT-32



Note:

1. Slashes (/) indicate tubes which will be inspected for denting (gauging program).
2. ⊡ --- Indicate previously plugged tubes.

INT-33



Note:

1. Slashes (/) indicate tubes which will be inspected for denting (gauging program).
2. ◘ -- Indicate previously plugged tubes.

SERIES 44

INT-34



Notes:

1. Tubes outside boundary lines 1 and 2 will be inspected for denting (gauging program). All the tubes which did not pass the previous (Mid-Cycle 3) #700 probe inspection are boxed-in.
2. Slashes (/) indicate tubes to be inservice inspected per IP-3, TS § 4.9 (this includes approx. 45 peripherical tubes gauge inspected).
3. ▣ Indicate previously plugged tubes.

SERIES 44

INT-31



Notes:

1. Slashes (/) indicate tubes which will be inspected for denting (gauging program).

2. ▩ Indicate previously plugged tubes.

SERIES 44

INT-32



Note:

1. Slashes (/) indicate tubes which will be inspected for denting (gauging program).
2. ▩ --- Indicate previously plugged tubes.

SERIES 44

INT-33



Note:

1. Slashes (/) indicate tubes which will be inspected for denting (gauging program).
2. ▣ -- Indicate previously plugged tubes.

SERIES 44

INT-34