William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

Regulatory File Cy.

April 8, 1977
Re: Indian Point Unit No. 2
Docket No. 50-247

RECEIVED APR 14 1977 U.S. NUCLEAR REGULATORY COMMISSION Mail Section

Mr. James P. O'Reilly, Director
Office of Inspection and Enforcement
Region 1
U.S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, PA 19406

Dear Mr. O'Reilly

The attached report (TEIR-77-2-1) is being submitted for your information.

Very truly yours,

William J. Cahill, Jr.
Vice President

8111040478 770408
PDR ADOCK ~~05000242~~ 50-247
S PDR

771050224

USNRC-REG. 1

11 APR 77 18 07

LICENSEE EVENT REPORT

TEIR-77-2-1

CONTROL BLOCK: (1–6)

(PLEASE PRINT ALL REQUIRED INFORMATION)

	LICENSEE NAME	LICENSE NUMBER	LICENSE TYPE	EVENT TYPE
01	NYIPS2	00-00000-00	4111	99
7–8	9–14	15–25	26–30	31–32

	CATEGORY	REPORT TYPE	REPORT SOURCE	DOCKET NUMBER	EVENT DATE	REPORT DATE
01 CON'T		O	L	050-024	030277	040877
7–8	57–58	59	60	61–68	69–74	75–80

EVENT DESCRIPTION

02 FOR INFORMATION ONLY - During normal operation, No. 21 diesel generator
03 was removed from service as a precautionary measure to allow replace-
04 ment of a lube oil filter Delta-P pressure switch. The diesel was
05 fully operable prior to its removal from service and was returned to an
06 operable condition within the time limit permitted by Tech. Specs.
[TEIR-77-2-1]

	SYSTEM CODE	CAUSE CODE	COMPONENT CODE	PRIME COMPONENT SUPPLIER	COMPONENT MANUFACTURER	VIOLATION
07	EE	E	INSTRU	N	A152	N
7–8	9–10	11	12–17	43	44–47	48

CAUSE DESCRIPTION

08 The internal diaphragm of an Alco, Type J21K, Model L-254-A-68, pres-
09 sure switch developed an oil leak, requiring switch replacement.
10

	FACILITY STATUS	% POWER	OTHER STATUS	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION
11	E	099	NA	B	Routine Inspection
7–8	9	10–12	13–44	45	46–80

	FORM OF ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY	LOCATION OF RELEASE
12	Z	Z	NA	NA
7–8	9	10	11–44	45–80

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION
13	000	Z	NA
7–8	9–11	12	13–80

PERSONNEL INJURIES

	NUMBER	DESCRIPTION
14	000	NA
7–8	9–11	12–80

PROBABLE CONSEQUENCES

15 NA

LOSS OR DAMAGE TO FACILITY

	TYPE	DESCRIPTION
16	Z	NA
7–8	9	10–80

PUBLICITY

17 NA

ADDITIONAL FACTORS

18 NA

19

NAME: Austin J. Decker II PHONE: 914-739-8823

GPO 881-667

RECEIVED DOCUMENT
PROCESSING UNIT

1977 APR/ MAR PM 4 2PM062 06