NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NYIPS2 (2) | 00-000000-00 (3) | 41111 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 REPORT SOURCE L (6) | 05000247 (7) | 121478 (8) | 011279 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 The fluid cylinder of No. 22 charging pump was recently replaced because
03 of the inability to fully eliminate leakage at the gasketed stuffing box
04 joint for the No. 1 plunger. At that time, the other two charging pumps
05 were operable. Followup NDT of the fluid cylinder revealed a hairline
06 crack in the No. 1 cylinder. This event is reportable in accordance
07 with the requirements of T.S. 6.9.1.7.2(d).
08

09 SYSTEM CODE PC (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE PUMPXX (14) | COMP. SUBCODE E (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 78 | — | SEQUENTIAL REPORT NO. 036 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER U055 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Dye checking indicated that a variable speed, positive displacement, 98
11 GPM Type QX-300 Quintuplex pump had developed a crack in its fluid head.
12 The head had been previously replaced and the pump returned to service.
13
14

15 FACILITY STATUS Z (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY C (31) | DISCOVERY DESCRIPTION (32) Dye Penetrant Testing

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY (43) TYPE Z (42) | DESCRIPTION NA

20 PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA

7901180176

NRC USE ONLY

NAME OF PREPARER John M. Makepeace PHONE: 914-739-8823

GPO 917-926