NRC FORM 366 (7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NYIPS2 (2) | 00-00000-00 (3) | 41111 (4) | (5)

LICENSEE CODE | LICENSE NUMBER | LICENSE TYPE | CAT

CON'T

01 | REPORT SOURCE L (6) | 05000247 (7) | 022279 (8) | 031679 (9)

DOCKET NUMBER | EVENT DATE | REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, a routine inspection of No. 21 service water
03 strainer indicated a ruptured gasket at the flange between the strainer
04 and its associated blowdown valve. Repairs necessitated the removal
05 of No. 21 service water pump from service. This pump serviced the
06 essential header. Following repairs, No. 21 service water pump was re-
07 turned to service, thereby reestablishing an essential header as per
08 T.S. 3.3.F.2.

09 | SYSTEM CODE WA (11) | CAUSE CODE E (12) | CAUSE SUBCODE B (13) | COMPONENT CODE PIPEXX (14) | COMP. SUBCODE A (15) | VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 79 | — | SEQUENTIAL REPORT NO. 011 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN A (18) | FUTURE ACTION Z (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS 0000 (22) | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. N (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER X999 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A service water pump was removed from service in order to replace a
11 ruptured gasket at the flange between a service water strainer and its
12 associated blowdown valve. The gasket was replaced in like and kind.
13
14

15 | FACILITY STATUS E (28) | % POWER 100 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Routine Inspection

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

PERSONNEL EXPOSURES

17 | NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

PERSONNEL INJURIES

18 | NUMBER 000 (40) | DESCRIPTION (41) NA

LOSS OF OR DAMAGE TO FACILITY (43)

19 | TYPE Z (42) | DESCRIPTION NA

PUBLICITY

20 | ISSUED N (44) | DESCRIPTION (45) NA

7903220214

NRC USE ONLY

NAME OF PREPARER John M. Makepeace PHONE: 914-739-8823

GPO 917-926