William J. Cahill, Jr.
Vice President

Consolidated Edison Company of New York, Inc.
4 Irving Place, New York, N Y 10003
Telephone (212) 460-3819

July 18, 1979
Re: Indian Point Unit No. 2
Docket No. 50-247

Mr. Darrell G. Eisenhut
Acting Director
Division of Operating Reactors
Office of Nuclear Reactor Regulation
U. S. Nuclear Regulatory Commission
Washington, D. C. 20555

REGULATORY DOCKET FILE COPY

Dear Mr. Eisenhut:

This letter is in response to I.E. Bulletin 79-01A (Items 1 and 3) and I.E. Bulletin 79-01 (Item 4). We have identified that the subject ASCO Solenoid Valves are in use in safety related systems at Indian Point Unit No. 2.

The unit is presently shutdown for a refueling/maintenance outage. We are evaluating this finding and will provide a detailed written report in accordance with I.E. Bulletin 79-01.

Very truly yours,

William J. Cahill, Jr.
Vice President

cc: Mr. Boyce H. Grier, Director
Office of Inspection and Enforcement
Region I
U. S. Nuclear Regulatory Commission
631 Park Avenue
King of Prussia, Pennsylvania, 19406

Mr. Ted Rebelowski, Resident Inspector
U. S. Nuclear Regulatory Commission
P. O. Box 38
Buchanan, N. Y. 10511

A005
1

7907250337