(7-77)

Update Report

LICENSEE EVENT REPORT

Previous Report Date 4/27/79

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 LICENSEE CODE: N Y I P S 2 (2) LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) LICENSE TYPE: 4 1 1 1 1 (4) CAT (5)

CON'T 01 REPORT SOURCE: L (6) DOCKET NUMBER: 0 5 0 0 0 2 4 7 (7) EVENT DATE: 0 3 2 9 7 9 (8) REPORT DATE: 1 2 2 1 7 9 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, a visual inspection revealed a pinhole leak at
03 a socket weld connection on the seal injection header (Line 402) down-
04 stream of the seal injection filters. Measured leakage was less than
05 one (1) gallon per hour (GPH). This event is reportable under the
06 provisions of Tech. Spec. 6.9.1.7.2.d.
07 Similar Event: LER-78-019/03.
08

09 SYSTEM CODE: P C (11) CAUSE CODE: E (12) CAUSE SUBCODE: C (13) COMPONENT CODE: P I P E X X (14) COMP. SUBCODE: A (15) VALVE SUBCODE: Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 7 9 — SEQUENTIAL REPORT NO. 0 1 3 / OCCURRENCE CODE 0 3 REPORT TYPE X — REVISION NO. 1

ACTION TAKEN: B (18) FUTURE ACTION: Z (19) EFFECT ON PLANT: Z (20) SHUTDOWN METHOD: Z (21) HOURS (22): 0 0 0 0 ATTACHMENT SUBMITTED: N (23) NPRD-4 FORM SUB.: N (24) PRIME COMP. SUPPLIER: N (25) COMPONENT MANUFACTURER: X 9 9 9 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 A socket weld associated with a 90-degree stainless steel elbow,
11 developed a pinhole leak. Initially a PLIDCO split collar was placed
12 around the elbow to control the leakage and assure the integrity of the
13 line. During our 1979 Refueling Outage, a permanent repair was accomp-
14 lished in which the affected socket weld joint was rewelded.

15 FACILITY STATUS: E (28) % POWER: 1 0 0 (29) OTHER STATUS (30): NA METHOD OF DISCOVERY: A (31) DISCOVERY DESCRIPTION (32): Visual Observation

16 ACTIVITY RELEASED: Z (33) CONTENT OF RELEASE: Z (34) AMOUNT OF ACTIVITY (35): NA LOCATION OF RELEASE (36): NA

17 PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) TYPE: Z (38) DESCRIPTION (39): NA

18 PERSONNEL INJURIES NUMBER: 0 0 0 (40) DESCRIPTION (41): NA

19 LOSS OF OR DAMAGE TO FACILITY (43) TYPE: Z (42) DESCRIPTION: NA

7912310 410

20 PUBLICITY ISSUED: N (44) DESCRIPTION (45): NA NRC USE ONLY

NAME OF PREPARER: John M. Makepeace PHONE: 914-739-8823

GPO 917-926