Docket No. 50-247

AUG 8 1972

Dr. Chester P. Siess
Chairman, Advisory Committee
on Reactor Safeguards
U. S. Atomic Energy Commission
Washington, D. C. 20545

Dear Dr. Siess:

Sixteen copies of the following are transmitted for review by the Committee:

CONSOLIDATED EDISON COMPANY OF NEW YORK, INC.
(Indian Point Nuclear Generating Unit 2)

Consolidated Edison Company's letter dated August 2, 1972, transmitting report entitled "Summary Report of Control Rod Drive Line Malfunction, Indian Point Unit No. 2".

Distribution:
Docket
PWR-2
KKniel
MService

Sincerely,

Richard C. DeYoung

Richard C. DeYoung, Assistant Director
for Pressurized Water Reactors
Directorate of Licensing

Enclosures:
As stated

8111230154 720808
PDR ADOCK 05000247
P PDR

OFFICE ▶	AD/PWRs XXXXXXXXX	PWR-2				
SURNAME ▶	MService:bn	KKniel				
DATE ▶	8/8/72	8/8/72				

Form AEC-318 (Rev. 9-53)

U.S. GOVERNMENT PRINTING OFFICE : 1966—O-214-629 929-542