
REGION R12
ERPA(s) to be Evacuated
Hytop
Stevenson
Skyline
Pleasant Groves
Hollywood
Pisgah
Ider
Scottsboro
Henagar
Dutton
Section
Sylvania
Langston
Powell
Rainsville
1
2
3
4
5
6
7
8
9
10
11
12
13
0 1 2 3 4 5
Miles
N
W
E
S