

(Reference 269)

FIGURE 2.5-243a
TVA Dam Safety Seismic Hazard Analysis Seismotectonic Source Zones