Western Union

Telegram

920P EST MAR 9 72 PB330

Q NNF457 (AT 069NN229457)PD IPMA58C NYK 0913P EST03/09/72

ZCZC 296 NYNC XNT2058 LR PDB FAX NEW YORK NY 9 506P EST

JAMES P O REILLY, DIRECTOR
DIVN OF COMPLIANCE REGION I
U. S. ATOMIC ENERGY COMMISSION
DELIVER ~~90~~ 970 BROAD ST NEWARK NJER 07107

BT

PURSUANT TO THE REQUIREMENTS OF THE TECHNICAL SPECIFICATIONS TO FACILITY OPERATING LICENSE NO. [illegible]R-26 PLEASE BE ADVISED THAT ON MARCH 8, 1972 A REACTOR COOLANT SYSTEM PRESSURE TRANSIENT FROM AN

SF-1201 (R5-69)

8111111007 720310
PDR ADOCK 05000247
Q PDR

western union Telegram

AS YET UNDETERMINED CAUSE WAS EXPERIENCED WITH THE
STARTING OF A REACTOR COLANT PUMP.
AT THE TIME OF
THE OCCURENCE, THE RESIDUAL HEAT REMOVAL SYSTEM WAS
IN SERVICE AT A TEMPERATURE AND PRESSURE OF 115OF AND
400 PSIG RESPECTIVELY. THE PRESSURE INCREASED REACHING
TERMINATED. IN LESS THAN A MINUTE THE PRESSURE WAS
REDUCED BELOW THE TECHNICAL SPECIFICATION LIMIT OF
500 PSIG.
THERE WAS NO APPARENT DAMAGE TO ANY SYSTEM OR COMPONENT
NOR WAS THERE REASON TO EXPECT ANY AS A RESULT OF THE
PRESSURE TRANSIENT. WE ARE CONTINUING OUR INVESTIGATION
TO THE ?CAUSE.
YOUR MR. GLEN MADSEN HAS BEEN INFORMED BY TELEPHONE

SF-1201 (R5-69)

Western Union Telegram

OF THE ABOVE OCCURENCE.
WILLIAM E CALDWELL JR
VICE PRESIDENT.

DPR-26 8 1972 115CF 400 640 500.

NNNN(0918P EST)

SF-1201 (R5-69)