NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NYIPS3 (2) | 00-00000-00 (3) | 41111 (4) | (5)
7 8 9 LICENSEE CODE 14 15 LICENSE NUMBER 25 26 LICENSE TYPE 30 57 CAT 58

CON'T
01 | REPORT SOURCE L (6) | 05000286 (7) | 082978 (8) | 092578 (9)
7 8 60 61 DOCKET NUMBER 68 69 EVENT DATE 74 75 REPORT DATE 80

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During restart power ascension past the 90 percent point, it was
03 observed while procedure 3PT-M34 was in progress, that No. 32
04 auxiliary boiler feed pump was unable to reach full discharge
05 pressure. However, two other feed pumps were operable thereby
06 satisfying Technical Specification requirements of 3.4.A.
07
08
7 8 9 80

09 | SYSTEM CODE HA (11) | CAUSE CODE E (12) | CAUSE SUBCODE E (13) | COMPONENT CODE TURBIN (14) | COMP. SUBCODE Z (15) | VALVE SUBCODE Z (16)
7 8 9 10 11 12 13 18 19 20

(17) LER/RO REPORT NUMBER | EVENT YEAR 78 | — | SEQUENTIAL REPORT NO. 024 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0
21 22 23 24 26 27 28 29 30 31 32

ACTION TAKEN X (18) | FUTURE ACTION B (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER W318 (26)
33 34 35 36 37 40 41 42 43 44 47

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Bearing failures in Worthington Turbine T2RA prevented turbine
11 from reaching rated speed. This caused pressure loss in
12 Worthington pump 4WTF 127. Both the pump and turbine were
13 disassembled and inspected. Repair of the turbine is in progress.
14
7 8 9 80

15 | FACILITY STATUS C (28) | % POWER 091 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Test
7 8 9 10 12 13 44 45 46 80

16 | ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA
7 8 9 10 11 44 45 80

17 | PERSONNEL EXPOSURES NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA
7 8 9 11 12 13 80

18 | PERSONNEL INJURIES NUMBER 000 (40) | DESCRIPTION (41) NA
7 8 9 11 12 80

19 | LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) | DESCRIPTION (43) NA
7 8 9 10 80

20 | PUBLICITY ISSUED N (44) | DESCRIPTION (45) NA
7 8 9 10 68 69 80

8111090264 780925
PDR ADOCK 05000286
S PDR

NRC USE ONLY

NAME OF PREPARER Floyd W. Gumble PHONE: 914-739-8200 X225

GPO 917-926