366

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

	Field	Value
01	LICENSEE CODE (2)	N Y I P 3
	LICENSE NUMBER (3)	0 0 0 0 0 0 0 0 0 0 0
	LICENSE TYPE (4)	4 1 1 1
	CAT (5)	
CON'T 01	REPORT SOURCE (6)	L
	DOCKET NUMBER (7)	0 5 0 0 0 2 8 6
	EVENT DATE (8)	0 8 1 5 7 8
	REPORT DATE (9)	0 9 1 5 7 8

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During preparation for plant startup, with the Reactor Coolant System in Hot
03 Shutdown, No. 32 RHR Pump Seal was found leaking. The pump was removed from service
04 to identify the cause of the leakage. No. 32 RHR Pump was repaired and returned to
05 service within the requirements of Tech. Spec. 3.3.A.4. No. 31 RHR Pump was verified
06 operable following removal of No. 32 Pump from service.
07
08

SYSTEM CODE (11)	CAUSE CODE (12)	CAUSE SUBCODE (13)	COMPONENT CODE (14)	COMP. SUBCODE (15)	VALVE SUBCODE (16)
C F	E	B	P U M P X X	B	Z

LER/RO REPORT NUMBER (17)

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
7 8	—	0 2 2	/	0 3	L	—	0

ACTION TAKEN (18)	FUTURE ACTION (19)	EFFECT ON PLANT (20)	SHUTDOWN METHOD (21)	HOURS (22)	ATTACHMENT SUBMITTED (23)	NPRD-4 FORM SUB. (24)	PRIME COMP. SUPPLIER (25)	COMPONENT MANUFACTURER (26)
A	Z	Z	Z	0 0 0 0	N	Y	N	I 0 7 5

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Upon disassembly of the No. 32 RHR Pump Seal it was found that the shaft sleeve
11 gasket was leaking and the seal faces were worn. The pump seal and gasket were
12 replaced. The pump was manufactured by Ingersoll-Rand, Model 8X20W.
13
14

15	FACILITY STATUS (28): G	% POWER (29): 0 0 0	OTHER STATUS (30): NA	METHOD OF DISCOVERY (31): A	DISCOVERY DESCRIPTION (32): Shift Supervisor Observation
16	ACTIVITY RELEASED (33): Z	CONTENT OF RELEASE (34): Z	AMOUNT OF ACTIVITY (35): NA		LOCATION OF RELEASE (36): NA

PERSONNEL EXPOSURES

17 NUMBER (37): 0 0 0 TYPE (38): Z DESCRIPTION (39): NA

PERSONNEL INJURIES

18 NUMBER (40): 0 0 0 DESCRIPTION (41): NA

LOSS OF OR DAMAGE TO FACILITY (43)

19 TYPE (42): Z DESCRIPTION: NA

PUBLICITY

20 ISSUED (44): N DESCRIPTION (45): NA

8111090286 780919
PDR ADOCK 05000286
SW PDR

NRC USE ONLY

NAME OF PREPARER John W. Kilduff PHONE: 914 739-8200 x 206

The last similar event was submitted as LER 78-006/03L

GPO 917-926