NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | NYIPS3 (2) | 00-00000-00 (3) | 41111 (4) | (5)
LICENSEE CODE (9–14) | LICENSE NUMBER (15–25) | LICENSE TYPE (26–30) | CAT (57–58)

CON'T 01 | REPORT SOURCE L (6) | 05000286 (7) | 050678 (8) | 060478 (9)
DOCKET NUMBER (61–68) | EVENT DATE (69–74) | REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During normal operation, LP Steam Dump Valve
03 No. 3 failed to open fully
04 during its stroke testing during performance
05 of PT-M24. Sufficient valves available to
06 operate at full power.
07
08

09 SYSTEM CODE HB (11) | CAUSE CODE X (12) | CAUSE SUBCODE Z (13) | COMPONENT CODE VALVEX (14) | COMP. SUBCODE F (15) | VALVE SUBCODE G (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 78 | — | SEQUENTIAL REPORT NO. 010 | / | OCCURRENCE CODE 03 | REPORT TYPE L | — | REVISION NO. 0

ACTION TAKEN Z (18) | FUTURE ACTION 0 (19) | EFFECT ON PLANT Z (20) | SHUTDOWN METHOD Z (21) | HOURS (22) 0000 | ATTACHMENT SUBMITTED N (23) | NPRD-4 FORM SUB. Y (24) | PRIME COMP. SUPPLIER N (25) | COMPONENT MANUFACTURER F130 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Repairs to be made during the next
11 refueling outage.
12
13
14

15 FACILITY STATUS E (28) | % POWER 091 (29) | OTHER STATUS (30) NA | METHOD OF DISCOVERY B (31) | DISCOVERY DESCRIPTION (32) Surveillance Test

16 ACTIVITY RELEASED Z (33) | CONTENT OF RELEASE Z (34) | AMOUNT OF ACTIVITY (35) NA | LOCATION OF RELEASE (36) NA

17 PERSONNEL EXPOSURES: NUMBER 000 (37) | TYPE Z (38) | DESCRIPTION (39) NA

18 PERSONNEL INJURIES: NUMBER 000 (40) | DESCRIPTION (41) NA

19 LOSS OF OR DAMAGE TO FACILITY: TYPE Z (42) | DESCRIPTION (43) NA

20 PUBLICITY: ISSUED N (44) | DESCRIPTION (45) NA

8111100157 780601
PDR ADOCK 05000286
S PDR

NRC USE ONLY

NAME OF PREPARER Neil A. Passman PHONE: 914-739-5177

GPO 917-926