LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

(2) LICENSEE CODE: N Y I P S 3 — (3) LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 — (4) LICENSE TYPE: 4 1 1 1 1 — (5) CAT

CON'T

REPORT SOURCE: L (6) — DOCKET NUMBER: 0 5 0 0 0 2 8 6 (7) — EVENT DATE: 0 4 0 5 7 9 (8) — REPORT DATE: 0 5 0 4 7 9 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While at 100 percent power, service water pump No. 34 was removed from service due to a low discharge pressure. It was determined upon investigation that the main pump shaft had broken, disabling one of the three essential header pumps required by Technical Specification 3.3.F.1. Plant operation was not affected by this incident. A similar event occurred on August 31, 1978 (LER 78-025/03L-0).

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
W A (11)	E (12)	B (13)	P U M P X X (14)	B (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
7 9	—	0 0 5	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X (18)	B (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	N (25)	L 0 9 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Service water pumps nos. 31, 32 and 33 were valved to the essential header at this point, and nos. 35 and 36 were valved to the nonessential header within the 8-hour Tech. Spec. limit. It was determined upon disassembly of the Verti-line, 350SW20K2 (Layne-Bowler) service water pump that bearing failures had caused the shaft to break. Repairs are pending.

FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
E (28)	1 0 0 (29)	NA	A (31)	Operator Observation

ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
Z (33)	Z (34)	NA	NA

PERSONNEL EXPOSURES

NUMBER	TYPE	DESCRIPTION (39)
0 0 0 (37)	Z (38)	NA

PERSONNEL INJURIES

NUMBER	DESCRIPTION (41)
0 0 0 (40)	NA

LOSS OF OR DAMAGE TO FACILITY

TYPE	DESCRIPTION (43)
Z (42)	NA

PUBLICITY

ISSUED	DESCRIPTION (45)
N (44)	NA

7905090305

NRC USE ONLY

NAME OF PREPARER Floyd Gumble PHONE: 914-739-8200 X217

GPO 917-926