

Figure 6-4. Hank Unit Radon, Gamma, and Air Particulate Monitoring Locations