NRC FORM 591M PART 1
(10-2003) 10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
Washtenaw County Road Commission 555 N. Zeeb Road Ann Arbor, MI REPORT NUMBER(S) 2010/001	U.S. Nuclear Regulatory Commission Region III 2443 Warrenville Road Suite 210 Lisle, Illinois 60532-4351

3. DOCKET NUMBER(S)	4. LICENSEE NUMBER(S)	5. DATE(S) OF INSPECTION
030-31116	21-26046-01	2/18/10

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

[X] 1. Based on the inspection findings, no violations were identified.

[ ] 2. Previous violation(s) closed.

[ ] 3. The violation(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, NUREG-1600, to exercise discretion, were satisfied.

_____ Non-Cited Violation(s) was/were discussed involving the following requirement(s) and Corrective Action(s):

[ ] 4. During this inspection certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11. (Violations and Corrective Actions)

Licensee's Statement of Corrective Actions for Item 4, above.

I hereby state that, within 30 days, the actions described by me to the inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

Title	Printed Name	Signature	Date
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Edward Kulzer	E. L. Kulzer	2/18/10

8pp

NRC FORM 591M PART 3
(10-2003) 10 CFR 2.201

Docket File Information

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE	2. NRC/REGIONAL OFFICE
Washtenaw County Road Commission REPORT NUMBER(S) 2010-001	**Region III** **2443 Warrenville Road, Suite 210** **Lisle, IL 60532**

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-31116	21-26046-01	Feb. 18, 2010

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
87124	03.01-03.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
3121	5	Michael Bernbeck	734.761.1500

[x] Main Office Inspection — Next Inspection Date: Feb.2015

[ ] Field Office

[ ] Temporary Job Site Inspection

PROGRAM SCOPE

The licensee is a county government engineering office located in Ann Arbor, Michigan. They perform soil density in the Corunna area. The licensee has three Troxler model 3440 series gauges. The gauges are stored at the licensee's facility. The licensee has five authorized gauge users who have completed the manufacturer's training.. The licensee does not perform any service or maintenance activities on the gauges.

Performance Observations

There were no temporary job sites at the time of the inspection. Interviews of licensee personnel indicated an adequate level of knowledge of radiation safety.

Independent surveys of the gauge storage area indicated that there were two locks securing the storage area. Personnel were monitored and had minimal exposures. The licensee secures the gauges in open bed pick up trucks using two locks and two chains. The gauge cases are also locked.

8/5