UNITED STATES

NUCLEAR REGULATORY COMMISSION

REGION IV

URANIUM RECOVERY FIELD OFFICE
BOX 25325
DENVER, COLORADO 80225

MAR 2 8 1993

URFO:DLJ
Docket No. 40 8914

MEMORANDUM FOR: Docket File No. 40-8914

FROM: Dawn L. Jacoby, Project Manager

SUBJECT: CLOSURE OF UNRESOLVED ITEM 40 8914/9102-02 RESULTING FROM THE JUNE 18, 1991, INSPECTION AT THE JOHNNY M MINE SITE

Inspection Report 40 8914/91 02 identified two unresolved items regarding contamination control during surface reclamation activities. Hecla Mining Company responded to the unresolved items in a letter dated July 18, 1991. The NRC, in a letter dated August 2, 1991, indicated that unresolved item 40 8914/9102 01 was considered closed based on review of the additional information.

Unresolved item 40-8914/9102 02 concerned the company's ALARA philosophy; specifically worker TLD badge policy. Hecla's response to unresolved item 40 8914/9102-02 was to be evaluated during a future inspection. All additional cleanup activities were completed before any followup inspection was performed, and the licensee response was sufficient to preclude escalation of the unresolved item. This item is closed.

Dawn L. Jacoby
Project Manager

9304120296 930328
PDR ADOCK 04008914
C PDR