

0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
Apex
B
L
M
Chatham
Pittsboro
Wake
F
Holly Springs
A
C
D
J
K
G
Fuquay Varina
Lee
I
H
Harnett
Johnston
Angier
REGION R15



0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
Apex
Pittsboro
Chatham
M
L
B
Wake
F
Holly Springs
A
C
D
J
K
G
Fuquay Varina
Lee
I
H
Harnett
Johnston
Angier
REGION R16



0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
L
M
A
C
D
K
J
G
F
H
I
Apex
Wake
Holly Springs
Chatham
Pittsboro
Fuquay Varina
Johnston
Angier
Harnett
Lee
REGION R17



0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
L
M
A
C
D
K
J
G
F
I
H
Apex
Wake
Holly Springs
Chatham
Pittsboro
Fuquay Varina
Johnston
Angier
Harnett
Lee
REGION R18


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
L
M
A
C
D
K
J
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
751
64
55
401
1
42
210
N
S
E
W
REGION R19


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
M
L
A
C
D
J
K
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
REGION R20
N
W
E
S


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
L
M
A
C
D
J
K
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
REGION R21