

PSEG Power, LLC

PSEG SITE ESPA

Part 2, Site Safety Analysis Report

Geotechnical Boring Location

FIGURE 2.5.1-37

Rev 0