
538000N
536000N
534000N
532000N
530000N
734000E
736000E
738000E
740000E
742000E
744000E
746000E
748000E
750000E
T25N
R93W
R92W
North Fault
Lost Creek Fault (main)
Lost Creek Fault (subsidiary)
South Fault
splinter fault
MU1
MU2
MU3
MU4
MU5
MU6
LOST CREEK PERMIT AREA
LOST CREEK PERMIT AREA
Sweetwater County, WYOMING
Test
Fault
Mineral Trend
LC5 Isopach Outline
Lost Creek ISR, LLC
Littleton, Colorado, USA
AATA INTERNATIONAL, INC.
Fort Collins, Colorado, USA
Legend
MU Proposed Mine Unit
Drill Hole (values < 10' thickness shown)
Fault
Thickness <10 feet
Thickness 10-20 feet
Thickness >20 feet
PLATE 2.6-2a
Isopach Map of the Lost Creek Shale
Lost Creek Permit Area
Issued For: NRC TR 1.0 Drawn By: CVH/cc
Issued/Revised: 11.13.07/04.08.10
Drawing No.: NRC TR 1.0 PLATE2.6-2a 04.08.10
D-01