
North Fault
Lost Creek Fault (subsidiary)
Lost Creek Fault (main)
splinter fault
South Fault
LOST CREEK PERMIT AREA
T25N
R93W
R92W
536000N
534000N
532000N
530000N
734000E
736000E
738000E
740000E
742000E
744000E
746000E
748000E
750000E
LOST CREEK PERMIT AREA
Sweetwater County
WYOMING
0 2,500 5,000
feet
Fault
Mineral Trend
HJ Structure Contour Outline
Lost Creek IBR, LLC
Littleton, Colorado, USA
SAFTA INTERNATIONAL, INC.
Fort Collins, Colorado, USA
Legend
Drill Hole
Fault
Contours, top of HJ sand; elevations in feet above msl
PLATE 2.6-4c
Structural Contour Map
HJ sand unit
Issued For: NRC TR 1.0 Drawn By: CVH/cc.
Issued/Revised: 02.26.09/04.12.10
Drawing No.: NRC TR1.0 PLATE2.6-4c 04.12.10
0 200 400
feet
D-03