**From:** Norman, Yolande
**To:** Castellon, Krupskaya;
**cc:** Norman, Yolande;
**Subject:** FW: Zone 3 injection testing report attached
**Date:** Thursday, August 12, 2010 11:38:18 AM

---

Could you please add the following document in ADAMs by 08/19. The document profile is as follows:

Title: RE: Zone 3 Injection Testing Report for the UNC Church Rock Mill Site. E-mail from Chester Engineers (Mark Jancin) to U.S. NRC (Yolande Norman) dated December 17, 2009.

License No.SUA-1475
Docket No. 040-08907

Document Profile
þ Publicly Available
þ Non-Sensitive
þ Immediate Release

Yolande J.C. Norman,
Project Manager
Division of Waste Management and Environmental Protection
Office of Federal and State Materials and Environmental Management Programs
U.S. Nuclear Regulatory Commission
Mail Stop T-8F5
11545 Rockville Pike
Rockville, Maryland 20852
Phone: (301) 415-7741
Fax: (301) 415-5369
yolande.norman@nrc.gov

---

**From:** Mark Jancin [mailto:mjancin@chesterengineers.com]
**Sent:** Thursday, December 17, 2009 4:12 PM
**To:** Norman, Yolande
**Subject:** RE: Zone 3 injection testing report attached

OK, will do.

---

**From:** Norman, Yolande [mailto:Yolande.Norman@nrc.gov]
**Sent:** Thursday, December 17, 2009 4:15 PM
**To:** Mark Jancin; Mark Purcell
**Cc:** earle.dixon@state.nm.us; Guo, Lifeng; Eugene Esplain; parr.buddy@epa.gov; Blickwedel, Roy (GE, Corporate); Bush, Larry (GE Infra, Aviation, US)
**Subject:** RE: Zone 3 injection testing report attached

Mark,

I need 2 two hard copies because the figures don't print very well on my printer. Thanks.

---

**From:** Mark Jancin [mailto:mjancin@chesterengineers.com]
**Sent:** Thursday, December 17, 2009 4:04 PM
**To:** Mark Purcell; Norman, Yolande
**Cc:** earle.dixon@state.nm.us; Guo, Lifeng; Eugene Esplain; parr.buddy@epa.gov; Blickwedel, Roy (GE, Corporate); Bush, Larry (GE Infra, Aviation, US)
**Subject:** Zone 3 injection testing report attached

Please note that this report is being submitted by email only. The report addresses the recent injection testing in well NBL-2 in the northern part of Zone 3 at the Church Rock tailings site. The report analysis is followed by a proposal to enhance the remediation in Zone 3 by the installation of new injection wells (subject to the results of a pilot well study in that new location).

**Mark Jancin, P.G.**
Project Manager

**Chester Engineers, Inc.**
1315 West College Ave., Suite 100
State College, PA 16801
Ph: 814-231-2170 x 20
Fax: 814-231-2174
mjancin@chesterengineers.com
www.chester-engineers.com

***"Tradition in Engineering Excellence Since 1910"***