

FIGURE 2.4.4-203
Fontana Dam - Postulated Condition of Dam after Failure OBE and One-Half Probable Maximum Flood