Attachment C

Greenhouses and Headhouse Wipe Data and Locations

All units of measure are dpm/100 cm^2
Unless otherwise indicated.

Abbreviations Used In Data Reports

R_b = Background counting rate (cpm)

Greenhouse Numbering System

G1, G3, etc. = Greenhouse number. Greenhouses are numbered 1, 2, 3 and 4.
The Roman numeral indicates the section within the greenhouse. Each greenhouse has 3 sections numbered I, II and III.
The Arabic numeral is the table number within that section.
Examples: G1 II 7 means Greenhouse 1, section II, table 7;
G3 1 10 means Greenhouse 3, section I, table 10.

F = floor

W = wall

L = overhead light fixture

C = ceiling components (e.g., pipes, metal supports)

HH = Head House

SR = Spray Room in the Head House

FR = Flammables Room in the Head House

CT – counter top

T = table

G2L = Greenhouse 2 Lab

GAR = Garage

LTS 3 = Lean-To storage area, shelf #3 (top)

LTF = Lean-To floor

WR = Weigh Room in the Head House;

COR = Corral
Within the Corral: BB = barrel bottoms, BT = barrel tops, WB = whole barrels

Other components are named or described.

Attachment C

RSA Laboratories

A Division of Radiation Safety Associates

Radiochemistry Analysis Data Sheet

Page 1 of 7

Report No. **Chemtura 1**
Customer: **Chemtura**
Customer Samp No. **W1 -W 619, W698 -W 848**
Location: **Bethany Greenhouse/Head House**
RSA Lab Sample No. **N/A**
Project: **Decomm.**
Date Collected: **10/29 - 10/31/2007**
Samp. Description: **Wipes**
Date Counted: **10/29 - 10/31/2007**
Matrix: **Wipes**

C-14 Background = 55.0 cpm **Count time = 1 min** **Efficiency = 95% (nominal)**

Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm
			W-36	G1II 2-4	19.00	W-72	G1III 1-4	13.90
W-1	G1I 6-1	14.1	W-37	G1II 4-1	19.20	W-73	G1III 3-1	12.40
W-2	G1I 6-2	11.1	W-38	G1II 4-2	1.60	W-74	G1III 3-2	1.30
W-3	G1I 6-3	13.9	W-39	G1II 4-3	5.70	W-75	G1III 3-3	16.10
W-4	G1I 6-4	20.1	W-40	G1II 4-4	20.70	W-76	G1III 3-4	5.40
W-5	G1I 8-1	5.5	W-41	G1II 6-1	15.70	W-77	G1III 5-1	21.90
W-6	G1I 8-2	23.3	W-42	G1II 6-2	16.30	W-78	G1III 5-2	3.00
W-7	G1I 8-3	13.7	W-43	G1II 6-3	3.20	W-79	G1III 5-3	3.60
W-8	G1I 8-4	8.9	W-44	G1II 6-4	9.00	W-80	G1III 5-4	0.00
W-9	G1I 10-1	20.2	W-45	G1II 7-1	28.40	W-81	G1I F-1	9.60
W-10	G1I 10-2	12.8	W-46	G1II 7-2	16.70	W-82	G1I F-2	14.80
W-11	G1I 10-3	11.9	W-47	G1II 7-3	2.20	W-83	G1I F-3	13.60
W-12	G1I 10-4	9.2	W-48	G1II 7-4	9.80	W-84	G1I F-4	13.00
W-13	G1I 12-1	11.3	W-49	G1II 1-1	13.40	W-85	G1I F-5	10.50
W-14	G1I 12-2	10.9	W-50	G1II 1-2	0.00	W-86	G1I F-6	58.70
W-15	G1I 12-3	0.6	W-51	G1II 1-3	16.80	W-87	G1II F-1	1.90
W-16	G1I 12-4	15.2	W-52	G1II 1-4	16.60	W-88	G1II F-2	2.90
W-17	G1I 3-1	6.3	W-53	G1II 5-1	23.00	W-89	G1II F-3	44.90
W-18	G1I 3-2	10.7	W-54	G1II 5-2	15.60	W-90	G1II F-4	10.70
W-19	G1I 3-3	6.9	W-55	G1II 5-3	0.00	W-91	G1II F-5	8.00
W-20	G1I 3-4	8.2	W-56	G1II 5-4	13.50	W-92	G1II F-6	39.40
W-21	G1I 5-1	3.4	W-57	G1III 2-1	3.60	W-93	G1III F-1	7.40
W-22	G1I 5-2	14.1	W-58	G1III 2-2	12.00	W-94	G1III F-2	25.50
W-23	G1I 5-3	6.8	W-59	G1III 2-3	15.30	W-95	G1III F-3	6.20
W-24	G1I 5-4	0	W-60	G1III 2-4	15.90	W-96	G1III F-4	13.00
W-25	G1I 7-1	10.9	W-61	G1III 4-1	13.70	W-97	G1III F-5	13.10
W-26	G1I 7-2	18.7	W-62	G1III 4-2	13.30	W-98	G1III F-6	12.70
W-27	G1I 7-3	0	W-63	G1III 4-3	15.90	W-99	G1I W-1	4.50
W-28	G1I 7-4	24.7	W-64	G1III 4-4	4.80	W-100	G1I W-2	10.60
W-29	G1I 9-1	2.7	W-65	G1III 6-1	21.30	W-101	G1I W-3	11.80
W-30	G1I 9-2	7	W-66	G1III 6-2	6.00	W-102	G1I W-4	17.60
W-31	G1I 9-3	4.3	W-67	G1III 6-3	14.00	W-103	G1I W-5	23.70
W-32	G1I 9-4	10.4	W-68	G1III 6-4	10.30	W-104	G1I W-6	11.30
W-33	G1II 2-1	0	W-69	G1III 1-1	0.00	W-105	G1II W-1	0.00
W-34	G1II 2-2	39.7	W-70	G1III 1-2	9.90	W-106	G1II W-2	2.90
W-35	G1II 2-3	15.2	W-71	G1III 1-3	3.40	W-107	G1II W-3	8.60

RSA Laboratories

A Division of Radiation Safety Associates

Radiochemistry Analysis Data Sheet

Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm
W-108	G1II W-4	13.40	W-154	G3I 8-2	22.40	W-200	G3II 1-4	10.70
W-109	G1II W-5	9.40	W-155	G3I 8-3	6.40	W-201	G3II 3-1	13.30
W-110	G1II W-6	16.40	W-156	G3I 8-4	15.30	W-202	G3II 3-2	19.40
W-111	G1III W-1	6.80	W-157	G3I 10-1	0.00	W-203	G3II 3-3	39.30
W-112	G1III W-2	13.90	W-158	G3I 10-2	8.50	W-204	G3II 3-4	15.90
W-113	G1III W-3	16.20	W-159	G3I 10-3	28.40	W-205	G3II 5-1	23.60
W-114	G1III W-4	3.30	W-160	G3I 10-4	17.60	W-206	G3II 5-2	14.00
W-115	G1III W-5	0.00	W-161	G3I 3-1	11.50	W-207	G3II 5-3	14.70
W-116	G1III W-6	25.90	W-162	G3I 3-2	31.00	W-208	G3II 5-4	17.10
W-117	G1I L-1	8.20	W-163	G3I 3-3	6.60	W-209	G3II 7-1	11.80
W-118	G1I L-2	7.20	W-164	G3I 3-4	11.60	W-210	G3II 7-2	13.70
W-119	G1I L-3	21.80	W-165	G3I 5-1	36.20	W-211	G3II 7-3	31.40
W-120	G1I L-4	25.50	W-166	G3I 5-2	12.90	W-212	G3II 7-4	25.80
W-121	G1II L-1	29.00	W-167	G3I 5-3	10.20	W-213	G3II 9-1	13.50
W-122	G1II L-2	12.00	W-168	G3I 5-4	5.00	W-214	G3II 9-2	10.10
W-123	G1II L-3	19.50	W-169	G3I 7-1	16.00	W-215	G3II 9-3	14.50
W-124	G1II L-4	11.80	W-170	G3I 7-2	3.60	W-216	G3II 9-4	16.70
W-125	G1III L-1	17.90	W-171	G3I 7-3	11.00	W-217	G3III 2-1	8.30
W-126	G1III L-2	13.30	W-172	G3I 7-4	9.20	W-218	G3III 2-2	0.00
W-127	G1III L-3	18.20	W-173	G3I 9-1	8.20	W-219	G3III 2-3	1.50
W-128	G1III L-4	12.60	W-174	G3I 9-2	9.90	W-220	G3III 2-4	0.00
W-129	G1I C-1	6.80	W-175	G3I 9-3	18.80	W-221	G3III 4-1	20.30
W-130	G1I C-2	4.50	W-176	G3I 9-4	14.10	W-222	G3III 4-2	18.50
W-131	G1I C-3	17.90	W-177	G3II 2-1	18.00	W-223	G3III 4-3	20.10
W-132	G1I C-4	15.70	W-178	G3II 2-2	16.10	W-224	G3III 4-4	10.20
W-133	G1II C-1	11.80	W-179	G3II 2-3	20.50	W-225	G3III 6-1	12.20
W-134	G1II C-2	0.00	W-180	G3II 2-4	0.00	W-226	G3III 6-2	0.00
W-135	G1II C-3	15.60	W-181	G3II 4-1	15.80	W-227	G3III 6-3	7.20
W-136	G1II C-4	16.20	W-182	G3II 4-2	0.00	W-228	G3III 6-4	8.30
W-137	G1III C-1	0.00	W-183	G3II 4-3	14.00	W-229	G3III 8-1	0.00
W-138	G1III C-2	12.60	W-184	G3II 4-4	0.00	W-230	G3III 8-2	28.70
W-139	G1III C-3	27.10	W-185	G3II 6-1	6.70	W-231	G3III 8-3	30.70
W-140	G1III C-4	5.80	W-186	G3II 6-2	43.10	W-232	G3III 8-4	0.00
W-141	G3I 2-1	29.00	W-187	G3II 6-3	14.50	W-233	G3III 10-1	26.40
W-142	G3I 2-2	13.80	W-188	G3II 6-4	0.00	W-234	G3III 10-2	18.50
W-143	G3I 2-3	22.90	W-189	G3II 8-1	17.40	W-235	G3III 10-3	6.30
W-144	G3I 2-4	10.10	W-190	G3II 8-2	13.30	W-236	G3III 10-4	21.00
W-145	G3I 4-1	10.90	W-191	G3II 8-3	18.10	W-237	G3III 1-1	10.50
W-146	G3I 4-2	14.00	W-192	G3II 8-4	15.80	W-238	G3III 1-2	10.40
W-147	G3I 4-3	2.80	W-193	G3II 10-1	0.00	W-239	G3III 1-3	13.10
W-148	G3I 4-4	25.70	W-194	G3II 10-2	15.00	W-240	G3III 1-4	12.30
W-149	G3I 6-1	15.80	W-195	G3II 10-3	18.40	W-241	G3III 3-1	30.50
W-150	G3I 6-2	14.20	W-196	G3II 10-4	16.00	W-242	G3III 3-2	11.70
W-151	G3I 6-3	8.10	W-197	G3II 1-1	10.60	W-243	G3III 3-3	0.00
W-152	G3I 6-4	12.80	W-198	G3II 1-2	10.80	W-244	G3III 3-4	0.00
W-153	G3I 8-1	14.80	W-199	G3II 1-3	28.90	W-245	G3III 5-1	16.60

Jay R. Dockendorff
Laboratory Director

RSA Laboratories

A Division of Radiation Safety Associates

Radiochemistry Analysis Data Sheet

Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm
W-246	G3III 5-2	0.00	W-292	G3III W-6	15.80	W-338	G2I 3-2	17.40
W-247	G3III 5-3	24.80	W-293	G3I C-1	0.00	W-339	G2I 3-3	19.80
W-248	G3III 5-4	11.20	W-294	G3I C-2	29.00	W-340	G2I 3-4	13.00
W-249	G3III 7-1	0.00	W-295	G3I C-3	5.20	W-341	G2I 5-1	2.00
W-250	G3III 7-2	11.10	W-296	G3I C-4	12.40	W-342	G2I 5-2	5.70
W-251	G3III 7-3	24.90	W-297	G3II C-1	3.00	W-343	G2I 5-3	26.20
W-252	G3III 7-4	18.50	W-298	G3II C-2	7.20	W-344	G2I 5-4	5.60
W-253	G3III 9-1	8.20	W-299	G3II C-3	20.30	W-345	G2I 7-1	12.00
W-254	G3III 9-2	6.90	W-300	G3II C-4	2.80	W-346	G2I 7-2	9.20
W-255	G3III 9-3	10.90	W-301	G3III C-1	29.10	W-347	G2I 7-3	11.90
W-256	G3III 9-4	10.60	W-302	G3III C-2	11.40	W-348	G2I 7-4	22.50
W-257	G3I F-1	19.80	W-303	G3III C-3	17.40	W-349	G2II 2-1	15.50
W-258	G3I F-2	0.00	W-304	G3III C-4	3.60	W-350	G2II 2-2	14.70
W-259	G3I F-3	12.80	W-305	G3I L-1	8.90	W-351	G2II 2-3	0.00
W-260	G3I F-4	12.70	W-306	G3I L-2	6.70	W-352	G2II 2-4	11.50
W-261	G3I F-5	12.70	W-307	G3I L-3	4.20	W-353	G2II 4-1	15.10
W-262	G3I F-6	11.60	W-308	G3I L-4	23.30	W-354	G2II 4-2	18.90
W-263	G3II F-1	18.50	W-309	G3II L-1	36.80	W-355	G2II 4-3	10.60
W-264	G3II F-2	0.00	W-310	G3II L-2	22.00	W-356	G2II 4-4	12.60
W-265	G3II F-3	34.30	W-311	G3II L-3	0.00	W-357	G2II 6-1	10.40
W-266	G3II F-4	28.70	W-312	G3II L-4	9.90	W-358	G2II 6-2	9.00
W-267	G3II F-5	5.30	W-313	G3III L-1	21.30	W-359	G2II 6-3	10.70
W-268	G3II F-6	13.30	W-314	G3III L-2	17.90	W-360	G2II 6-4	12.80
W-269	G3III F-1	8.60	W-315	G3III L-3	11.00	W-361	G2II 8-1	13.60
W-270	G3III F-2	0.00	W-316	G3III L-4	7.90	W-362	G2II 8-2	23.80
W-271	G3III F-3	9.10	W-317	G2I 2-1	32.20	W-363	G2II 8-3	23.90
W-272	G3III F-4	7.30	W-318	G2I 2-2	22.00	W-364	G2II 8-4	16.90
W-273	G3III F-5	12.40	W-319	G2I 2-3	25.90	W-365	G2II 10-1	21.00
W-274	G3III F-6	12.70	W-320	G2I 2-4	12.10	W-366	G2II 10-2	21.40
W-275	G3I W-1	1.10	W-321	G2I 4-1	9.30	W-367	G2II 10-3	5.40
W-276	G3I W-2	9.60	W-322	G2I 4-2	10.70	W-368	G2II 10-4	13.00
W-277	G3I W-3	21.90	W-323	G2I 4-3	15.00	W-369	G2II 1-1	16.80
W-278	G3I W-4	0.00	W-324	G2I 4-4	15.50	W-370	G2II 1-2	17.80
W-279	G3I W-5	13.90	W-325	G2I 6-1	1.20	W-371	G2II 1-3	26.10
W-280	G3I W-6	12.80	W-326	G2I 6-2	11.10	W-372	G2II 1-4	20.30
W-281	G3II W-1	16.60	W-327	G2I 6-3	4.30	W-373	G2II 3-1	3.90
W-282	G3II W-2	13.30	W-328	G2I 6-4	34.50	W-374	G2II 3-2	0.00
W-283	G3II W-3	0.20	W-329	G2I 8-1	14.10	W-375	G2II 3-3	5.60
W-284	G3II W-4	17.00	W-330	G2I 8-2	37.60	W-376	G2II 3-4	9.40
W-285	G3II W-5	11.50	W-331	G2I 8-3	13.30	W-377	G2II 5-1	0.00
W-286	G3II W-6	16.00	W-332	G2I 8-4	13.90	W-378	G2II 5-2	12.90
W-287	G3III W-1	0.00	W-333	G2I 1-1	0.00	W-379	G2II 5-3	13.10
W-288	G3III W-2	16.90	W-334	G2I 1-2	12.20	W-380	G2II 5-4	10.60
W-289	G3III W-3	12.60	W-335	G2I 1-3	20.70	W-381	G2II 7-1	13.50
W-290	G3III W-4	15.40	W-336	G2I 1-4	14.10	W-382	G2II 7-2	30.20
W-291	G3III W-5	22.70	W-337	G2I 3-1	32.90	W-383	G2II 7-3	61.40

Jay R. Dockendorff
Laboratory Director

Attachment C

RSA Laboratories

A Division of Radiation Safety Associates

Radiochemistry Analysis Data Sheet

Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm
W-384	G2II 7-4	4.40	W-430	G2II F-4	0.00	W-476	G2II L-4	3.10
W-385	G2II 9-1	10.50	W-431	G2II F-5	11.70	W-477	G2III L-1	0.90
W-386	G2II 9-2	15.40	W-432	G2II F-6	11.20	W-478	G2III L-2	12.10
W-387	G2II 9-3	7.70	W-433	G2III F-1	18.90	W-479	G2III L-3	11.20
W-388	G2II 9-4	0.00	W-434	G2III F-2	6.50	W-480	G2III L-4	35.40
W-389	G2III 2-1	14.60	W-435	G2III F-3	20.70	W-481	G4I 1	12.90
W-390	G2III 2-2	14.60	W-436	G2III F-4	14.20	W-482	G4I 3	11.60
W-391	G2III 2-3	9.70	W-437	G2III F-5	24.10	W-483	G4I 4	20.30
W-392	G2III 2-4	2.00	W-438	G2III F-6	12.80	W-484	G4I 5	18.20
W-393	G2III 4-1	13.80	W-439	G2I W-1	25.20	W-485	G4I F	28.50
W-394	G2III 4-2	17.40	W-440	G2I W-2	26.00	W-486	G4I C	0.00
W-395	G2III 4-3	16.80	W-441	G2I W-3	5.30	W-487	G4I L	86.60
W-396	G2III 4-4	12.30	W-442	G2I W-4	12.30	W-488	G4II 4	20.90
W-397	G2III 6-1	17.30	W-443	G2I W-5	19.80	W-489	G4II 6	10.00
W-398	G2III 6-2	13.00	W-444	G2I W-6	46.60	W-490	G4II 9	1.40
W-399	G2III 6-3	6.50	W-445	G2II W-1	18.40	W-491	G4II 5	18.20
W-400	G2III 6-4	28.70	W-446	G2II W-2	14.60	W-492	G4II F	0.40
W-401	G2III 8-1	9.10	W-447	G2II W-3	13.70	W-493	G4II C	0.00
W-402	G2III 8-2	16.00	W-448	G2II W-4	20.80	W-494	G4II L	26.30
W-403	G2III 8-3	12.10	W-449	G2II W-5	7.70	W-495	G4III 2	14.10
W-404	G2III 8-4	39.40	W-450	G2II W-6	9.80	W-496	G4III 6	19.60
W-405	G2III 1-1	26.00	W-451	G2III W-1	25.70	W-497	G4III 1	24.30
W-406	G2III 1-2	14.90	W-452	G2III W-2	10.90	W-498	G4III F	0.00
W-407	G2III 1-3	9.70	W-453	G2III W-3	12.00	W-499	G4III C	17.70
W-408	G2III 1-4	22.60	W-454	G2III W-4	11.30	W-500	G4III L	5.00
W-409	G2III 3-1	28.20	W-455	G2III W-5	9.20	W-501	SR F1	9.80
W-410	G2III 3-2	11.00	W-456	G2III W-6	19.00	W-502	SR F2	3.40
W-411	G2III 3-3	10.50	W-457	G2I C-1	15.10	W-503	SR F3	1.20
W-412	G2III 3-4	9.90	W-458	G2I C-2	6.00	W-504	SR F4	13.20
W-413	G2III 5-1	9.40	W-459	G2I C-3	12.50	W-505	SR F5	8.20
W-414	G2III 5-2	19.20	W-460	G2I C-4	5.80	W-506	SR F6	13.20
W-415	G2III 5-3	10.70	W-461	G2II C-1	11.80	W-507	SR CT1	9.70
W-416	G2III 5-4	26.90	W-462	G2II C-2	3.00	W-508	SR Sink	12.30
W-417	G2III 7-1	7.10	W-463	G2II C-3	12.90	W-509	SR CT2	0.80
W-418	G2III 7-2	15.20	W-464	G2II C-4	0.00	W-510	SR CT3	2.60
W-419	G2III 7-3	0.00	W-465	G2III C-1	5.90	W-511	Sprayer Back L	12.90
W-420	G2III 7-4	22.60	W-466	G2III C-2	15.70	W-512	Sprayer Back L	27.30
W-421	G2I F-1	17.30	W-467	G2III C-3	14.40	W-513	Sprayer Floor L	10.60
W-422	G2I F-2	17.10	W-468	G2III C-4	11.20	W-514	Sprayer Floor R	2.60
W-423	G2I F-3	0.60	W-469	G2I L-1	21.80	W-515	Sprayer Glass I L	5.50
W-424	G2I F-4	12.80	W-470	G2I L-2	13.50	W-516	Sprayer Glass I R	14.90
W-425	G2I F-5	18.20	W-471	G2I L-3	0.00	W-517	Sprayer Rack L	60.00
W-426	G2I F-6	10.80	W-472	G2I L-4	15.40	W-518	Sprayer Rack R	18.60
W-427	G2II F-1	9.80	W-473	G2II L-1	9.20	W-519	Sprayer Front L	14.50
W-428	G2II F-2	18.10	W-474	G2II L-2	25.50	W-520	Sprayer Front R	23.90
W-429	G2II F-3	9.00	W-475	G2II L-3	68.90	W-521	FR F-1	12.00

Jay R. Dockendorff
Laboratory Director

Attachment C

RSA Laboratories

A Division of Radiation Safety Associates

Radiochemistry Analysis Data Sheet

Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm
W-522	FR F-2	62.70	W-568	WR C-1	6.10	W-614	COR Tray 1	23.10
W-523	FR F-3	0.00	W-569	WR Comp	10.60	W-615	COR Tray 2	10.60
W-524	FR F-4	18.90	W-570	WR Robot	13.90	W-616	COR Tray 3	36.40
W-525	FR Cab 1	12.00	W-571	WR C-2	9.70	W-617	COR Tray 4	36.40
W-526	FR Cab 2	3.30	W-572	WR Sink	11.70	W-618	CORSaw	15.30
W-527	FR Cab 3	13.90	W-573	WR Cab 1	16.20	W-619	COR Meter Stick	3.10
W-528	FR Cab 4	2.00	W-574	WR Cab 2	16.00	WIPE NUMBERS 620 - 697 NOT USED		
W-529	FR Cab 5	17.50	W-575	WR Cab 3	17.20			
W-530	FR Cab 6	9.70	W-576	COR BB 1	22.30	CONTINUED NEXT PAGE		
W-531	FR Cab 7	7.30	W-577	COR BB 2	21.50			
W-532	FR Cab 8	25.70	W-578	COR BB 3	4.70			
W-533	G2L T	12.40	W-579	COR BB 4	9.50			
W-534	G2L F-1	9.80	W-580	COR BB 5	21.10			
W-535	G2L F-2	31.30	W-581	COR BB 6	10.70			
W-536	G2L F-3	27.20	W-582	COR BB 7	19.70			
W-537	G2L CT 1	10.30	W-583	COR BB 8	20.90			
W-538	G2L CT 2	21.60	W-584	COR BB 9	8.60			
W-539	G2L CT 3	13.60	W-585	COR BB 10	14.20			
W-540	G2L Sink	11.40	W-586	COR BB 11	9.70			
W-541	GAR F-1	7.60	W-587	COR BT 1	13.40			
W-542	GAR F-2	1.50	W-588	COR BT 2	14.90			
W-543	GAR F-3	1.50	W-589	COR BT 3	4.10			
W-544	GAR F-4	8.90	W-590	COR BT 4	8.50			
W-545	GAR F-5	14.10	W-591	COR BT 5	1.90			
W-546	GAR F-6	10.70	W-592	COR BT 6	11.70			
W-547	GAR F-7	0.50	W-593	COR BT 7	17.00			
W-548	GAR F-8	8.90	W-594	COR BT 8	76.70			
W-549	GAR F-9	26.20	W-595	COR BT 9	28.60			
W-550	GAR F-10	15.60	W-596	COR BT 10	0.00			
W-551	GAR F-11	14.60	W-597	COR BT 11	9.40			
W-552	GAR F-12	5.90	W-598	COR BT 12	5.20			
W-553	GAR F-13	20.50	W-599	COR WB 1	2.10			
W-554	GAR F-14	0.00	W-600	COR WB 2	20.40			
W-555	LTS 3-1	11.70	W-601	COR Long ShovEL	17.80			
W-556	LTS 3-2	5.90	W-602	COR Short Shovel	22.20			
W-557	LTS 2-1	12.50	W-603	COR Spade	13.70			
W-558	LTS 2-2	0.80	W-604	COR Pot	14.60			
W-559	LTS 1-1	33.70	W-605	COR Bucket	19.60			
W-560	LTS 1-2	8.30	W-606	COR Rad Jug	0.00			
W-561	LT F-1	8.10	W-607	COR Corer	7.80			
W-562	LT F-2	10.80	W-608	COR Shed 1	1.20			
W-563	G3 Hose	4.00	W-609	COR Shed 2	7.70			
W-564	WR F-1	0.00	W-610	COR Shed 3	9.60			
W-565	WR F-2	0.50	W-611	COR Shed 4	15.60			
W-566	WR F-3	10.80	W-612	COR Shed 5	9.90			
W-567	WR F-4	35.20	W-613	COR Shed 6	13.00			

Jay R. Dockendorff
Laboratory Director

Attachment C

RSA Laboratories

A Division of Radiation Safety Associates

Radiochemistry Analysis Data Sheet

Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm
W-698	G1HH Chiller Controls	66.80	W-744	G1HH Hood back	0.00
W-699	G1HH Top 2 Shelves	6.80	W-745	G1HH Hood L side	16.00
W-700	G1HH Bottom 2 Shelves	12.30	W-746	G1HH Hood R side	0.00
W-701	G1HH Table East 1/2	13.40	W-747	G1HH Hood top of baffle	1.80
W-702	G1HH Table West 1/2	18.90	W-748	G1HH Hood inside glass	6.20
W-703	G1HH Bench L end	8.10	W-749	G1HH Hood back	18.80
W-704	G1HH Bench Middle	25.00	W-750	G1HH Cabinet under hood	26.50
W-705	G1HH Bench end	27.50	W-751	G1HH Cabinet under hood	11.40
W-706	G1HH Top 2 Drawers	7.00	W-752	G1HH Shelf	19.50
W-707	G1HH Bottom 2 dr. & Cabinet	6.20	W-753	G1HH Floor	2.50
W-708	G1HH Counter East 1/2	26.70	W-754	G1HH Floor	29.20
W-709	G1HH Counter West 1/2	8.00	W-755	G1HH Floor	14.70
W-710	G1HH Upper Cabinet	30.50	W-756	G1HH Floor	6.50
W-711	G1HH SE Floor	0.00	W-757	G1HH Floor	9.60
W-712	G1HH NE Floor	16.30	W-758	G1HH Floor	31.80
W-713	G1HH SE Mid Floor	10.40	W-759	G1HH Counter top	13.70
W-714	G1HH NE Mid Floor	14.20	W-760	G1HH Counter top	8.40
W-715	G1HH S Doorway & Floor	15.50	W-761	G1HH Floor	23.70
W-716	G1HH N Doorway & Floor	12.30	W-762	G1HH Floor	20.70
W-717	G1HH SW Floor	0.00	W-763	G1HH Hood	20.20
W-718	G1HH NW Floor	5.80	W-764	G1HH Hood	19.40
W-719	G1HH Ramp & Floor	8.30	W-765	G1HH Hood	23.40
W-720	G1HH Floor under Table	15.20	W-766	G1HH Hood	15.00
W-721	G3HH Floor	0.00	W-767	G1HH Hood	12.60
W-722	G3HH Floor	28.70	W-768	G1HH Hood	2.10
W-723	G3HH Floor	18.90	W-769	G1HH Hood	5.20
W-724	G3HH Sink	11.50	W-770	G1HH Hood	36.50
W-725	G3HH Sink Drain	10.00	W-771	G1HH Hood	0.00
W-726	G3HH Floor	1.30	W-772	G1HH Hood	12.10
W-727	G3HH Counter top	16.40	W-773	G1HH Hood	13.70
W-728	G3HH Counter top	6.20	W-774	G1HH Hood	22.20
W-729	G3HH Cabinet Shelf 2	17.60	W-775	G1HH Cabinet	5.90
W-730	G3HH Floor	1.10	W-776	G1HH Cabinet	9.70
W-731	G3HH Cabinet under counter	0.00	W-777	G1HH Counter top	5.60
W-732	G3HH Door under counter	12.60	W-778	G1HH Sink	9.20
W-733	G3HH Cabinet under counter	13.80	W-779	G1HH Drain	36.40
W-734	G3HH Counter top	4.30	W-780	G1HH Counter top	14.80
W-735	G3HH Counter top	12.60	W-781	G1HH Sink	14.50
W-736	G3HH Floor	0.00	W-782	G1HH Drain	2.70
W-737	G3HH Floor	18.80	W-783	G1HH Floor	21.50
W-738	G3HH Door under counter	4.80	W-784	G1HH Floor	19.00
W-739	G3HH Door under counter	0.90	W-785	G1HH Floor	12.70
W-740	G3HH Cabinet under counter	14.60	W-786	G1HH Sink	25.80
W-741	G1HH Hood lip	27.20	W-787	G1HH Drain	0.00
W-742	G1HH Hood base	21.00	W-788	G1HH Inside dishwasher	0.00
W-743	G1HH Hood base	20.20	W-789	G1HH Top of dishwasher	21.90

Jay R. Dockendorff
Laboratory Director

RSA Laboratories

A Division of Radiation Safety Associates

Radiochemistry Analysis Data Sheet

Page 7 of 7

Wipe #	Location	C-14 dpm	Wipe #	Location	C-14 dpm
W-790	G1HH Sink	21.20	W-825	G2HH Shipping table	15.30
W-791	G1HH Drain	7.00	W-826	G2HH Floor	17.40
W-792	G1HH Drawer	9.20	W-827	G2HH Counter	18.60
W-793	G1HH Drawer	24.40	W-828	G2HH Counter	5.80
W-794	G1HH Drawer	14.80	W-829	G2HH Counter	11.00
W-795	G1HH Eyewash Station	9.50	W-830	G2HH Counter	0.10
W-796	G2HH Hood # 3	24.10	W-831	G2HH Drawer/Cabinet	0.00
W-797	G2HH Hood # 3	39.00	W-832	G2HH Drawer/Cabinet	39.90
W-798	G2HH Hood # 3	9.30	W-834	G2HH Drawer/Cabinet	11.70
W-799	G2HH Hood # 3	13.80	W-835	G2HH Floor	22.80
W-800	G2HH Hood # 3	14.40	W-836	G2HH Floor	40.10
W-801	G2HH Hood # 3	0.00	W-837	G2HH Floor	57.50
W-802	G2HH Hood # 3	23.60	W-838	G2HH Floor	19.40
W-803	G2HH Hood # 3	22.40	W-839	G2HH Top of cabinet	0.00
W-804	G2HH Hood # 3	8.30	W-840	G2HH Inside cabinet	0.00
W-805	G2HH Hood # 3	15.70	W-841	G2HH Inside dew chamber	16.20
W-806	G2HH Hood # 3	8.70	W-842	G2HH Inside dew chamber	4.30
W-807	G2HH Hood # 3	12.60	W-843	G2HH Inside dew chamber	5.30
W-808	G2HH Counter	15.80	W-844	G2HH Inside dew chamber	18.50
W-809	G2HH Floor under counter	10.80	W-845	G2HH Outside door dew chamber	10.00
W-810	G2HH Floor	19.90	W-846	G2HH Outside door dew chamber	29.70
W-811	G2HH Inside oven	0.00	W-847	G2HH Outside oven door	1.20
W-812	G2HH Inside oven	16.50	W-848	G2HH Outside oven door	7.30
W-813	G2HH Shelf	0.00			
W-814	G2HH Floor	8.20			
W-815	G2HH Floor	8.00			
W-816	G2HH Counter	9.00			
W-817	G2HH Counter	33.70			
W-818	G2HH Floor	11.50			
W-819	G2HH Floor	29.20			
W-820	G2HH Floor	19.60			
W-821	G2HH Receiving table	0.00			
W-822	G2HH Floor	12.00			
W-823	G2HH Floor	4.40			
W-824	G2HH Floor	12.90			


GREENHOUSE # 1
SECTION III
SECTION II
SECTION I
Floors and Walls
(All numbers are wipe sample locations.)


GREENHOUSE # 1
SECTION III
SECTION II
SECTION I
126
6
138
125
4
2
137
128
5
140
3
127
139
1
7
134
122
6
121
4
2
133
124
5
136
135
123
1
12
131
118
10
8
117
6
129
120
9
132
7
5
3
130
119
Lights and Ceiling
(All numbers are wipe sample locations.)


GREENHOUSE # 2
(All numbers are wipe sample locations.)
SECTION III
SECTION II
SECTION I
Floors and Walls
455
436
456
438
404
403
401
402
8
420
417
419
418
7
434
400
399
397
398
6
416
413
415
414
5
453
454
396
395
393
394
4
412
409
411
410
3
435
437
433
391
451
392
390
389
2
408
405
406
452
407
1
367
449
368
366
365
10
385
388
386
450
387
9
428
364
363
361
8
430
384
381
383
7
432
447
362
382
360
359
357
358
6
380
448
377
379
5
378
356
355
353
354
4
429
376
373
375
3
431
427
351
445
352
350
349
2
369
372
370
446
371
1
331
332
443
330
329
8
345
348
346
444
347
7
422
328
327
325
326
6
424
344
341
343
5
426
441
342
442
324
323
321
322
4
423
340
337
339
3
425
338
320
319
317
318
2
421
336
333
335
1
334
439
440


GREENHOUSE # 2
SECTION III
SECTION II
SECTION I
466
478
8
6
477
4
465
2
480
468
7
5
3
467
479
1
474
10
462
8
6
461
473
4
2
9
464
476
7
475
5
463
3
1
8
458
470
6
4
457
469
2
472
7
460
5
471
3
459
1
Lights and Ceiling
(All numbers are wipe sample locations.)


GREENHOUSE # 3
(All numbers are wipe sample locations.)
SECTION III
SECTION II
SECTION I
Floors and Walls
10
9
8
7
6
5
4
3
2
1
235 236 234 291 233
253 256 254 292 255
270
231 272 232 229 230
249 252 251 250
227 289 228 225 226
245 274 248 247 246
290
223 224 221 222 271
241 244 243 242 273
269
219 287 220 218 217
237 288 240 238 239
195 196 194 285 193
213 216 214 286 215
264
191 266 192 189 190
209 212 268 211 210
283 187 188 185 186
205 208 284 207 206
183 184 181 182 265
201 204 203 202 267
263
179 180 178 281 177
197 282 200 198 199
159 160 158 279 157
173 176 174 280 175
258
155 260 156 153 154
169 172 262 171 170
151 277 152 149 150
165 168 278 167 166
147 259 148 145 146
161 164 163 162
257
143 411 142 275 141
276 261

GREENHOUSE # 3

(All numbers are wipe sample locations.)




GREENHOUSE # 4
(All numbers are wipe sample locations.)
SECTION III
SECTION II
SECTION I
QUARANTINE ROOM
CULTURE ROOM
Floors and Walls
6
4
2
10
8
6
4
2
6
5
4
3
2
1
5
3
1
9
7
5
3
1
4
496
495
498
500
499
497
490
494
489
493
492
491
488
487
484
483
482
486
485
481


GH 1
hood 2
hood 1
HEADHOUSE 1
Connect to "A"
(All numbers are wipe sample locations.)
Offices
Basement
HEADHOUSE 2
GH 2
hood 3
Connect to "B"
Connect to "A"
To Loading Dock
780
777
758
752
781
782
778
779
792
793
757
755
753
783
785
762
756
754
784
760
760
786
790
791
787
761
760
759
789
830
829
828
827
823
817
816
814
808
831
832
833
834
818
809
824
815
810
837
836
835
819
845
846
849
812
848
811
822
838
843
841
825
821
813
844
842
826
840
820



Hood 1



Hood 3



(All numbers are wipe sample locations.)

Hood 2


GH 3
HEADHOUSE 3
Connect to "C"
Connect to "B"
729
728
727
724
731
732
733
725
730
ramp
737
726
722
(All numbers are wipe sample locations.)
Weigh Room
738
739
740
736
735
734
723
Upstairs
Furnace Room
GH 4
698
699
700
717
701
702
711
713
715
720
712
714
716
718
719
ramp
Connect to "C"
707
706
703
710
704
705
708
709
Sprayer Room
Weigh Room
Head House


GREENHOUSE # 3
Post-Decon
SECTION III
SECTION II
SECTION I
55 56 57 52 53 54 8
49 50 51 46 47 48 6
40 41 42 34 35 36 4
31 32 33 2
43 44 45 37 38 39 3
25 26 27 10
28 29 30 9
22 23 24 19 20 21 8
16 17 18 13 14 15 4
7 8 9 2
10 11 12 1
1 2 3 10
4 5 6 9
(All numbers are wipe sample locations.)


569
568
564
570
565
572
Shelves
567
566
571
Weigh Room
573
574
575
GH 2
540
533
534
535
536
Greenhouse 2 Lab
537
538
539
GH 3
Flammable Cabinet 1
Flammable Cabinet 2
Flammable Cabinet 3
Flammable Cabinet 4
521
525
529
522
526
530
523
527
531
524
528
532
Flammable Room
(All numbers are wipe sample locations.)



(All numbers are wipe sample locations.)





Garage

(All numbers are wipe sample locations.)



Lean-to Shelf & Floor