
0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
M
L
A
C
D
J
K
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
751
64
55
401
1
42
210
N
S
E
W
REGION R19


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
M
L
A
C
D
J
K
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
REGION R20


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
M
L
A
C
D
J
K
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
REGION R21


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
M
L
A
C
D
J
K
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
REGION R22
N
W
E
S


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
M
L
A
C
D
J
K
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
REGION R23
N
S
E
W


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
M
L
A
C
D
J
K
G
I
H
F
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
REGION R24
N
S
E
W


0 1 2 3 4 5
Miles
Legend
Harris Nuclear Plant
2,5, & 10 Mile Rings
Sub-Zone Boundary
Sub-Zone(s) to be Evacuated
N
E
B
M
L
A
C
D
J
K
G
F
I
H
Pittsboro
Chatham
Apex
Wake
Holly Springs
Fuquay-Varina
Lee
Harnett
Johnston
Angier
REGION R25
N
S
E
W