From: Lloyd Flowers [lloyd.flowers@ezag.com]
Sent: Thursday, July 07, 2011 12:02 PM
To: Bermudez, Hector
Subject: RE: Return Packing List

Hector Bermudez,

The source in question was returned to EZIP for recycling. When the source arrives, a wipe of the outer package is conducted.
If this wipe is "clean" we open the package, remove the source and submit it to our HP Department for recycling.
We don't wipe the source unless there is a report that there is a leak or damage. The source appeared to be fine.

Thank you,

Lloyd

From: Bermudez, Hector [mailto:Hector.Bermudez@nrc.gov]
Sent: Thursday, July 07, 2011 8:42 AM
To: Lloyd Flowers
Subject: RE: Return Packing List

Thanks for your prompt response. However, I had access to that document and the issue raised was whether the source had a negative wipe test result. If you look at the rest of the sources in that shipment, the documents clearly specify that they had been wipe tested with less than 5 nCi results. Is there any way to confirm that particular source was OK?

From: Lloyd Flowers [mailto:lloyd.flowers@ezag.com]
Sent: Thursday, July 07, 2011 11:36 AM
To: Bermudez, Hector
Subject: Return Packing List

,

Please see the attached Return Packing List from Champlain Valley Cardiovascular.

Thank you,

Lloyd L. Flowers
Quality Systems Manager
Eckert & Ziegler Isotope Products
Ph. 661-309-1010
Fax 818-558-5980