

Figure 3E.1-14—Reinforcement Pattern for Section 3-3 of the Equipment Hatch Area






Figure 3E.1-15—Elevation View of the Entire RCB



UJA029 T2




Figure 3E.1-16—Section Cut Through Entire RCB



UJA030 T2



Figure 3E.1-17—Elevation View of Critical Section



UJA031 T2