NRC FORM 567
(9-2012)

U.S. NUCLEAR REGULATORY COMMISSION

REQUEST FOR A SEALED SOURCE OR DEVICE EVALUATION

INSTRUCTIONS: Send this request AND a copy of all related letters/applications and drawings to the Chief, Sealed Source Safety Section, OWFN Mail Stop O-6 H3. Change the License Tracking System milestone to 19 and assign to reviewer code 1-5.
NOTE: Retain a copy of this request with the application and background files.

REQUESTER		REGION/LOCATION:
Bruker Daltonics, Inc.		☐ I ☐ II ☐ III ☐ IV ☐ OCHCO ☐ LFARB
TELEPHONE NUMBER: (510) 683-4337	DATE:	
NAME OF APPLICANT: Colin D'Silva		**TYPE OF ACTION REQUESTED** *(Check as appropriate)*
MAIL CONTROL NUMBER(S): 581468		☐ SOURCE REVIEW ☐ AMENDMENT OF REGISTRATION SHEET NUMBER(S)
LETTER/APPLICATION DATE: 6/28/2013	LICENSE NUMBER(S): New	☑ DEVICE REVIEW New ☐ CUSTOM REVIEW

COMMENTS:
3500 West Warren Avenue
Fremont, CA 94538

FOR SSSS USE ONLY

REVIEWER	MODEL NUMBERS	NUMBER ASSIGNED
Maria Arribas-Colon & J. Jankovich	Electron Capture Detector	13-29
DATE RECEIVED	**DATE ASSIGNED**	**DATE TO FEES**
8/2/2013	8/2/2013	8/2/2013

TYPE OF ACTION *(Indicate the number of each type)*

☑ COMMERCIAL DISTRIBUTION (FORMAL) ☐ USE BY A SINGLE APPLICANT (CUSTOM)

SOURCE (9C)	DEVICE (9A)	SOURCE (9D)	DEVICE (9B)
☐ NEW	☑ NEW	☐ NEW	☐ NEW
☐ AMENDMENT	☐ AMENDMENT	☐ AMENDMENT	☐ AMENDMENT

☐ NO SAFETY EVALUATION REQUIRED
NO FEES REQUIRED

☑ LICENSING ACTION REQUIRED (IF KNOWN) ☑ YES ☐ NO

☑ OTHER *(Specify)*
Credit Card payment of $7,700 made for SSD review and Credit Card payment made of $4,300 for E-License review.

	TOTAL NUMBER OF REVIEW HOURS	NOTES Bruker Daltonics, Inc. (New), Dkt. 030-38672, MC #581468 - New SSD Application too.
	NUMBER OF DEFICIENCY LETTERS	
	NUMBER OF DEFICIENCY CALLS	ADAMS Package: ML13214A440

FOR FEE USE ONLY

TYPE OF FEE		FEE CATEGORY			
		☑ 9A	☐ 9B	☐ 9C	☐ 9D
AMOUNT RECEIVED	CHECK NUMBER	DATE OF CHECK		LOG	
APPROVED BY				DATE OF RETURN	
COMMENTS					