






LEGEND

- 1-km (0.6-mi.) Radius from Site
- AP1000 Structures
- Postulated Faults
Ticks indicate downthrown side.
(Source: Vernon, 1951)
- Regional Fractures
(Source: Vernon, 1951)
- Lineaments
(Source: Florida DOT, 1973)

2 ft. LIDAR DEM
Elevation (NAVD 88)



Basemap: LIDAR (Aero-Metric, 2007) and
National Elevation Dataset
(USGS, 1999)



Duke Energy Florida
**Levy Nuclear Plant
Units 1 and 2
Part 2, Final Safety Analysis Report**

Postulated Faults and Fractures (Lineaments)
within the LNP Site Area Shown on Hillshade
Relief Map Derived from LIDAR Data
FIGURE 2.5.3-214 Rev 6