ACCELERATED DISTRIBUTION DEMONSTRATION SYSTEM

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9002270213 DOC.DATE: 90/02/16 NOTARIZED: NO DOCKET #
FACIL:50-361 San Onofre Nuclear Station, Unit 2, Southern Californ 05000361
50-362 San Onofre Nuclear Station, Unit 3, Southern Californ 05000362
AUTH.NAME AUTHOR AFFILIATION
NANDY,F.R. Southern California Edison Co.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Informs that submittal of rept summarizing evaluation of non-1E devices in component cooling water sys will be delayed until approx 900308,due to determination that addl confirmatory evaluations should be performed.

DISTRIBUTION CODE: A001D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1
TITLE: OR Submittal: General Distribution

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD5 LA	1	1	PD5 PD	1	1
	KOKAJKO,L.	5	5			
INTERNAL:	ACRS	6	6	NRR/DET/ECMB 9H	1	1
	NRR/DOEA/OTSB11	1	1	NRR/DST 8E2	1	1
	NRR/DST/SELB 8D	1	1	NRR/DST/SICB 7E	1	1
	NRR/DST/SRXB 8E	1	1	NUDOCS-ABSTRACT	1	1
	OC/LFMB	1	0	OGC/HDS2	1	0
	REG FILE 01	1	1	RES/DSIR/EIB	1	1
EXTERNAL:	LPDR	1	1	NRC PDR	1	1
	NSIC	1	1			

RIDS/ADDS

RIDS/ADDS

2nd distribution for additional docket

NOTE TO ALL "RIDS" RECIPIENTS:

PLEASE HELP US TO REDUCE WASTE! CONTACT THE DOCUMENT CONTROL DESK, ROOM P1-37 (EXT. 20079) TO ELIMINATE YOUR NAME FROM DISTRIBUTION LISTS FOR DOCUMENTS YOU DON'T NEED!

TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL ~~25~~ 0

MAIL

Southern California Edison Company

23 PARKER STREET

IRVINE, CALIFORNIA 92718

F. R. NANDY
MANAGER OF NUCLEAR LICENSING

TELEPHONE
(714) 587-5400

February 16, 1990

U. S. Nuclear Regulatory Commission
Attention: Document Control Desk
Washington, D. C. 20555

Gentlemen:

Subject: Docket Nos. 50-361 and 50-362
Component Cooling Water System
TAC Nos. 71194 and 71195
San Onofre Nuclear Generating Station
Units 2 and 3

An operability assessment of the San Onofre Units 2 and 3 Component Cooling Water (CCW) System identified a potential problem with valves in this system having non-Class 1E powered control circuits. This condition was identified in LER 88-034 dated January 16, 1989. As a result of this LER, SCE initiated an evaluation of the non-1E devices in the CCW system. The purpose of this letter is to inform you that submittal of the report summarizing this evaluation will be delayed.

During our final engineering review of this report, it was determined that additional confirmatory evaluations should be performed for two of the non-1E devices discussed in the report. This evaluation and subsequent review are projected to require an additional three weeks. Although no changes are expected to the overall conclusions documented in the current draft of the report, it is considered appropriate to obtain the results of the additional confirmatory evaluations prior to finalizing the report. Therefore, submittal of this report will be delayed until approximately March 8, 1990.

If you have any questions regarding this information, please call me.

Very truly yours,

JLR:becCCWS4&5

cc: J. B. Martin, Regional Administrator, NRC Region V
C. Caldwell, NRC Senior Resident Inspector, San Onofre
Units 1, 2 and 3

9002270213 900216
PDR ADOCK 05000361
P PNU

A001
1/0