REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8404190322 DOC.DATE: 84/04/13 NOTARIZED: NO DOCKET #
FACIL:50-261 H. B. Robinson Plant, Unit 2, Carolina Power and Ligh 05000261
AUTH.NAME AUTHOR AFFILIATION
SIMMERMAN,S.R. Carolina Power & Light Co.
RECIP.NAME RECIPIENT AFFILIATION
VARGA,S.A. Operating Reactors Branch 1

SUBJECT: Forwards amended pages to revised inservice insp & test program for pumps & valves,per 840113 submittal.Info changes test frequency for safety injection sys valve 869 from cold shutdown to quarterly.

DISTRIBUTION CODE: A047S COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 3
TITLE: OR Submittal: Inservice Inspection/Testing

NOTES:

	RECIPIENT ID CODE/NAME		COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME		COPIES LTTR	COPIES ENCL
	NRR ORB1 BC	01	7	7				
INTERNAL:	ELD/HDS1		1	0	NRR/DE/MEB	15	1	1
	~~NRR/DE/MTEB~~	14	1	1	NRR/DL/TAPMG		1	1
	REG FILE	04	1	1	RGN2		1	1
EXTERNAL:	ACRS	16	10	10	LPDR	03	1	1
	NRC PDR	02	1	1	NSIC	05	1	1
	NTIS		1	1				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 27 ENCL 26

CP&L
Carolina Power & Light Company

APR 13 1984

SERIAL: NLS-84-144

Director of Nuclear Reactor Regulation
Attention: Mr. Steven A. Varga, Chief
Operating Reactors Branch No. 1
Division of Licensing
United States Nuclear Regulatory Commission
Washington, DC 20555

H. B. ROBINSON STEAM ELECTRIC PLANT, UNIT NO. 2
DOCKET NO. 50-261/LICENSE NO. DPR-23
IN-SERVICE INSPECTION AND TEST PROGRAM

Dear Mr. Varga:

By letter dated January 13, 1984, Carolina Power & Light Company submitted the revised In-Service Inspection and Test Program for Pumps and Valves for the H. B. Robinson Steam Electric Plant Unit No. 2. Recent reviews have indicated the need for two revisions.

1) On Table 3, page 2 of 4, the test frequency for Safety Injection System Valve 869 is being changed from cold shutdown to quarterly.

2) Safety Injection System Valve 869 is being deleted from Table 4, on page 5 of 6, since this table concerns only equipment for which the test frequency is cold shutdown.

Please replace the pages from our January 13, 1984 submittal with those attached.

If you have any further questions on this subject, please contact a member of our Nuclear Licensing Staff.

Yours very truly,

S. R. Zimmerman
Manager
Nuclear Licensing Section

ONH/ccc (9787ONH)
Enclosures

cc: Mr. J. P. O'Reilly (NRC-RII)
Mr. G. Requa (NRC)
Mr. Steve Weise (NRC-HBR)

8404190322 840413
PDR ADOCK 05000261
Q PDR

A047

411 Fayetteville Street • P. O. Box 1551 • Raleigh, N. C. 27602

TABLE 3 VALVE TEST PROGRAM
H. B. ROBINSON STEAM ELECTRIC PLANT UNIT NO. 2

System Name Safety Injection P&ID No. ISI-200-5379-1082, Sh. 1

Valve Number	Class	Drawing Coordinates	Valve Category				Passive	Size (inches)	Valve Type	Actuator Type	Normal Position	High Radiation Area	Test Method	Test Frequency	Relief Request	Max. Stroke Time (sec.)	Remarks
			A	B	C	D											
867A	2	F-7		X				4	GA	MO	CL	Y	S T VI	Q Q Q		10	P.T. 2.7A
867B	2	F-7		X				4	GA	MO	CL	Y	S T VI	Q Q Q		10	P.T. 2.7A
869	2	B-1	X					3	GA	MO	O	N	S T VI J	Q Q Q J	 1	60	
870A	2	G-1	X					3	GA	MO	CL	N	S T VI J	Q Q Q J	 1	10	P.T. 2.7A
870B	2	G-1	X					3	GA	MO	CL	N	S T VI J	Q Q Q J	 1	10	P.T. 2.7A
871	2	K-14			X			3/4X1	RV	SA	CL	N	RV	X			P.T. 25.4
872	3	H-6			X			3/4x1	RV	SA	CL	N	RV	X			P.T. 25.4
878A	2	F-10		X				4	GA	MO	O	N	S T VI	C C C		120	P.T. 42.0

SYSTEM	VALVE	DESCRIPTION	REMARKS
Safety Injection	865A, B, C	Accumulator Discharge Isolation	Same as for 864A, B.
Safety Injection	878A, B	SI Pump Discharge Header Cross Connect	Same as for 864A, B.
Safety Injection	873A, B, C, D, E, F	High Head SI to RCS Cold Legs Check Valves	See Relief Request 4.
Safety Injection	874A, B	High Head SI to RCS Hot Legs Check Valves	See Relief Request 4.
Safety Injection	863A, B	RHR Pumps Discharge to SI Pumps Suction Isolation	Per Tech. Spec. 3.3.1.1.h, during conditions of operation with reactor coolant pressure in excess of 1,000 psig, the A.C. control power shall be removed from these valves with the valves in the closed position. Cycling of these valves during normal operation would violate Tech. Spec.
Safety Injection	866A, B	High Head SI to RCS Hot Legs Isolation	Same as for 863A, B.
Safety Injection	879A, B, C	SI Pumps Discharge Check Valves	See Relief Request 7.
Safety Injection	876A, B, C	RHR Pump Discharge to RCS Loop Cold Leg Check valves	These valves cannot be full stroke exercised during normal operation due to the difference in the pressure between the RCS (2235 psig) and the discharge head of the RHR pumps (160 psig).
Safety Injection	870C, D	Spray Additive Tank Vacuum Breakers	See Relief Request 11.

bs