UNITED STATES
NUCLEAR REGULATORY COMMISSION
REGION IV
1600 E LAMAR BLVD
ARLINGTON, TX 76011-4511

July 28, 2014

Mr. Tom Palmisano
Senior Vice President and
Chief Nuclear Officer
Southern California Edison Company
San Onofre Nuclear Generating Station
P.O. Box 128
San Clemente, CA 92674-0128

SUBJECT: CLOSURE OF INVESTIGATION (OI 4-2012-038)

Dear Mr. Palmisano:

This refers to an investigation conducted by the NRC's Office of Investigations regarding activities at San Onofre Nuclear Generating Station. The Office of Investigations initiated the investigation to determine if a senior engineer or other Southern California Edison Company employees at the San Onofre Nuclear Generating Station, San Clemente, California, willfully failed to provide complete and accurate information to NRC inspectors.

Based on the evidence developed during this investigation, the allegation a senior engineer or other Southern California Edison Company employees at the San Onofre Nuclear Generating Station willfully failed to provide complete and accurate information to NRC inspectors was not substantiated. The NRC plans no further action related to the alleged wrongdoing and considers this investigation closed.

You should note that final NRC documents may be made available to the public under the Freedom of Information Act subject to redaction of information pursuant to the Freedom of Information Act. Requests under the Freedom of Information Act should be made in accordance with 10 CFR 9.23, Requests for Records. Information is accessible from the NRC's website at http://www.nrc.gov/reading-rm/foia/foia-request.html#how.

In accordance with 10 CFR 2.390 of the NRC's "Rules of Practice," a copy of this letter will be made available electronically for public inspection in the NRC Public Document Room or from the NRC's Agencywide Documents Access and Management System (ADAMS), accessible from the NRC website at http://www.nrc.gov/reading-rm/adams.html.

Sincerely,

Vivian H. Campbell, Chief
Allegation and Enforcement Branch

Dockets: 50-361; 50-362
Licenses: NPF-10; NPF-15