Tier / Group	Randomly Selected K/A	Reason for Rejection
1/1	295027 K2.01	Not Applicable to Fermi – Not Mark III Containment
2/1	207000	Not Applicable to Fermi – Isolation (Emergency) Condenser
2/1	209002	Not Applicable to Fermi - HPCS
2/2 (RO)	288000 G.02.25	Oversampled, changed to 288000 G.02.40
1/1 (RO)	295023 G.02.37	Contractor provided question with K/A information without password protection. Question was discarded and K/A randomly reselected to 295023 G.02.39
2/2 (RO)	288000 G.02.40	K/A not performed by RO at Fermi (SRO ONLY), randomly selected new K/A 28800 G.01.27
2/1(SRO)	203000 A.02.08	No operationally valid question could be written. Randomly selected 203000 A2.10.
N/A	205000 A4.01	JPM selected for RO (d. Place Div 1 RHR in SDC Following Removal For <2 Hrs) overlapped with a question on the written exam. Selected another JPM within Safety Function 4 (Manually Initiate Core Spray System with Core Spray B & D Breakers Trip) with K/A of 209001 A4.01.
N/A	N/A	Due to identified overlap between one written exam question and an evaluated event, replaced CST Level Instrument malfunction in Scenario #1 with a Main Steam Line Flow Transmitter failure event. This changed the evaluated Tech Spec and some minor operator actions.
3 (RO)	G.01.34	Selected K/A was not operationally valid for ROs at Fermi. Randomly selected new K/A G.01.19.
1/1	700000 AA2.09	No operationally valid question could be written. Randomly selected 700000 AA2.01.