NRC FORM 591M PART 1
(07-2012)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
Quality Testing Services, Inc. 2305 Millpark Drive Maryland Heights, Missouri 63043-3529 REPORT NUMBER(S) 2016-001	Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-35610	24-32292-01	06/28/2016

LICENSEE:

The inspection was an examination of the activities conducted under your license as they relate to radiation safety and to compliance with the Nuclear Regulatory Commission (NRC) rules and regulations and the conditions of your license. The inspection consisted of selective examinations of procedures and representative records, interviews with personnel, and observations by the inspector. The inspection findings are as follows:

☑ 1. Based on the inspection findings, no violations were identified.

☑ 2. Previous violation(s) closed.

☐ 3. The violations(s), specifically described to you by the inspector as non-cited violations, are not being cited because they were self-identified, non-repetitive, and corrective action was or is being taken, and the remaining criteria in the NRC Enforcement Policy, to exercise discretion, were satisfied.

_____ Non-cited violation(s) were discussed involving the following requirement(s):

☐ 4. During this inspection, certain of your activities, as described below and/or attached, were in violation of NRC requirements and are being cited in accordance with NRC Enforcement Policy. This form is a NOTICE OF VIOLATION, which may be subject to posting in accordance with 10 CFR 19.11.
(Violations and Corrective Actions)

Statement of Corrective Actions

I hereby state that, within 30 days, the actions described by me to the Inspector will be taken to correct the violations identified. This statement of corrective actions is made in accordance with the requirements of 10 CFR 2.201 (corrective steps already taken, corrective steps which will be taken, date when full compliance will be achieved). I understand that no further written response to NRC will be required, unless specifically requested.

TITLE	PRINTED NAME	SIGNATURE	DATE
LICENSEE'S REPRESENTATIVE			
NRC INSPECTOR	Bill C. Lin		7/7/16
BRANCH CHIEF	Aaron T. McCraw	Deborah A. Stone for AT McCraw	7/12/16

NRC FORM 591M PART 3
(07-2012)
10 CFR 2.201

U.S. NUCLEAR REGULATORY COMMISSION

Docket File Information

SAFETY INSPECTION REPORT AND COMPLIANCE INSPECTION

1. LICENSEE/LOCATION INSPECTED:	2. NRC/REGIONAL OFFICE
Quality Testing Services, Inc. 2305 Millpark Drive Maryland Heights, Missouri 63043-3529 REPORT NUMBER(S) 2016-001	Region III U. S. Nuclear Regulatory Commission 2443 Warrenville Road, Suite 210 Lisle, IL 60532-4352

3. DOCKET NUMBER(S)	4. LICENSE NUMBER(S)	5. DATE(S) OF INSPECTION
030-35610	24-32292-01	06/28/2016

6. INSPECTION PROCEDURES USED	7. INSPECTION FOCUS AREAS
87121	3.01-3.07

SUPPLEMENTAL INSPECTION INFORMATION

1. PROGRAM CODE(S)	2. PRIORITY	3. LICENSEE CONTACT	4. TELEPHONE NUMBER
03320	1	David J. Prohaska	(314) 770-0607

- [x] Main Office Inspection — Next Inspection Date: 06/28/2017
- [ ] Field Office Inspection
- [ ] Temporary Job Site Inspection

PROGRAM SCOPE

This was a routine inspection of a radiography licensee located in Maryland Heights, Missouri. The licensee currently possesses two iridium 192 (Ir-192) radiography exposure devices and is staffed with six radiographers. The licensee is authorized to conduct radiography operations at temporary job sites.

Performance Observation

At the time of the inspection, the NRC inspector did not have the opportunity to observe the performance of an industrial radiography operation at a temporary job site. The inspector toured the facilities of the main office and performed radiation surveys of the storage area. The inspection also included a review of selected records such as dosimetry, radiographer field audits, quarterly inventories and maintenance, leak tests, survey instrument and dosimetry calibrations, annual audits and radiation safety training, Department of Transportation training, survey records and daily utilization logs. The inspector also interviewed several qualified radiographers regarding the licensee's Emergency Operating procedures.

No violations of NRC requirements were identified.