REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8002220378 DOC.DATE: 80/02/14 NOTARIZED: NO DOCKET #
FACIL:50-220 Nine Mile Point Nuclear Station, Unit 1, Niagara Powe 05000220
AUTH.NAME AUTHOR AFFILIATION
DISE,D.P. Niagara Mohawk Power Corp.
RECIP.NAME RECIPIENT AFFILIATION
* Office of Nuclear Reactor Regulation
IPPOLITO,T. Operating Reactors Branch 3

SUBJECT: Responds to 800110 request for review of facility control rod failures to fully insert during 1978 & 1979.Review indicates that at no time did control rod fail to insert or malfunction on scram.

DISTRIBUTION CODE: A001S COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1
TITLE: General Distribution for after Issuance of Operating Lic

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
ACTION:	05 BC ORB #3	7	7			
INTERNAL:	01 REG FILE	1	1	02 NRC PDR	1	1
	12 I&E	2	2	15 CORE PERF BR	1	1
	17 ENGR BR	1	1	18 REAC SFTY BR	1	1
	19 PLANT SYS BR	1	1	20 EEB	1	1
	21 EFLT TRT SYS	1	1	EPB-DOR	1	1
	OELD	1	0	STS GROUP LEADR	1	1
EXTERNAL:	03 LPDR	1	1	04 NSIC	1	1
	23 ACRS	16	16			

FEB 25 1980

MA
4

TOTAL NUMBER OF COPIES REQUIRED: LTTR 38 ENCL ~~37~~ 0

NIAGARA MOHAWK

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

February 14, 1980

Director of Nuclear Reactor Regulation
Attention: Mr. Thomas Ippolito, Chief
Operating Reactors
Branch #3
U. S. Regulatory Commission
Washington, D. C. 20555

Re: Nine Mile Point Unit 1
Docket No. 50-220
DPR-63

Gentlemen:

Your letter of January 10, 1980 requested a review for Nine Mile Point Unit 1 regarding instances in which the control rods failed to fully insert during 1978 and 1979. Review of that data indicates that at no time did a control rod fail to insert or malfunction on scram.

Very truly yours,

NIAGARA MOHAWK POWER CORPORATION

Donald P. Dise

Donald P. Dise,
Vice President Engineering

SWW:jk

A001 S/D

D

8 002220

378