NIAGARA MOHAWK

NIAGARA MOHAWK POWER CORPORATION/300 ERIE BOULEVARD WEST, SYRACUSE, N.Y. 13202/TELEPHONE (315) 474-1511

September 6, 1984
(NMP2L 0150)

Mr. R. W. Starostecki, Director
U. S. Nuclear Regulatory Commission
Region I
Division of Project and Resident Programs
631 Park Avenue
King of Prussia, PA 19406

RE: Nine Mile Point - Unit 2
Docket No. 50-410/84-30

Dear Mr. Starostecki:

Enclosed is an interim report in accordance with 10CFR50.55(e) for the problem concerning the use of a nonqualified breaker in a Quality Assurance Category I battery charger. This problem was reported by G. Griffith (Niagara Mohawk Licensing) to P. Russ of your staff on August 7, 1984.

Very truly yours,

C. V. Mangan
Vice President
Nuclear Engineering and Licensing

CVM/GG/pbd

xc: Director of Inspection and Enforcement
U. S. Nuclear Regulatory Commission
Washington, DC 20555

R. A. Gramm, NRC Resident Inspector

Project File (2)

IE 27

NIAGARA MOHAWK POWER CORPORATION
NINE MILE POINT - UNIT 2
DOCKET NO. 50-410

Interim Report for a Problem Concerning the Use
of Nonqualified Breakers in Battery Charges
(55(e)-84-30)

Description of the Problem

An inspection of the Division III battery chargers 2BYS*CHGR2C1 and 2BYS*CHGR2C2 indicated that the dc circuit breakers actually provided were different than those shown on the bill of material. The vendor was required to provide qualified Class 1E circuit breakers manufactured by Westinghouse. Correct dc circuit breakers were identified on the bill of material, but the battery chargers supplied to the Nine Mile Point 2 site were equipped with nonqualified Square D dc circuit breakers.

The matter is still under investigation and a final report will be submitted by November 19, 1984.