CATEGORY 1

REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:9711030221 DOC.DATE: 97/10/28 NOTARIZED: NO DOCKET #
FACIL:50-410 Nine Mile Point Nuclear Station, Unit 2, Niagara Moha 05000410
AUTH.NAME AUTHOR AFFILIATION
SYLVIA,B.R. Niagara Mohawk Power Corp.
RECIP.NAME RECIPIENT AFFILIATION
Document Control Branch (Document Control Desk)

SUBJECT: Forwards LER 97-002-03 re potential inoperability of EDG svc water cooling outlet valves during control room fire. Supplemental LER updates Section III Analysis based upon completed evaluations.

DISTRIBUTION CODE: IE22T COPIES RECEIVED:LTR 1 ENCL 1 SIZE: 148
TITLE: 50.73/50.9 Licensee Event Report (LER), Incident Rpt, etc.

NOTES:

	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME	COPIES LTTR	COPIES ENCL
	PD1-1 PD	1	1	HOOD,D	1	1
INTERNAL:	ACRS	1	1	AEOD/SPD/RAB	2	2
	AEOD/SPD/RRAB	1	1	FILE CENTER	1	1
	NRR/DE/ECGB	1	1	NRR/DE/EELB	1	1
	NRR/DE/EMEB	1	1	NRR/DRCH/HHFB	1	1
	NRR/DRCH/HICB	1	1	NRR/DRCH/HOLB	1	1
	NRR/DRCH/HQMB	1	1	NRR/DRPM/PECB	1	1
	NRR/DSSA/SPLB	1	1	NRR/DSSA/SRXB	1	1
	RES/DET/EIB	1	1	RGN1 FILE 01	1	1
EXTERNAL:	L ST LOBBY WARD	1	1	LITCO BRYCE,J H	1	1
	NOAC POORE,W.	1	1	NOAC QUEENER,DS	1	1
	NRC PDR	1	1	NUDOCS FULL TXT	1	1

C A T E G O R Y 1 D O C U M E N T

NOTE TO ALL "RIDS" RECIPIENTS:
PLEASE HELP US TO REDUCE WASTE. TO HAVE YOUR NAME OR ORGANIZATION REMOVED FROM DISTRIBUTION LISTS OR REDUCE THE NUMBER OF COPIES RECEIVED BY YOU OR YOUR ORGANIZATION, CONTACT THE DOCUMENT CONTROL DESK (DCD) ON EXTENSION 415-2083

FULL TEXT CONVERSION REQUIRED
TOTAL NUMBER OF COPIES REQUIRED: LTTR 25 ENCL 25

A04

NIAGARA MOHAWK
GENERATION
BUSINESS GROUP

NUCLEAR LEARNING CENTER, 450 LAKE ROAD, OSWEGO, NY 13126/TELEPHONE (315) 349-2882

B. RALPH SYLVIA
Executive Vice President
Electric Generation
Chief Nuclear Officer

October 28, 1997
NMP2L 1733

U. S. Nuclear Regulatory Commission
Attn: Document Control Desk
Washington, DC 20555

RE: Docket No. 50-410
LER 97-02
Supplement 3

Gentlemen:

In accordance with 10CFR50.73 (a)(2)(i)(B) and 10CFR50.73 (a)(2)(ii)(B), we are submitting LER 97-02, Supplement 3 "Potential Inoperability of Emergency Diesel Generator Service Water Cooling Outlet Valves During a Control Room Fire." This supplement is submitted to update Section III Analysis based upon completed evaluations of the Emergency Diesel Generator loading and flow response of valves 2SWP*MOV66A and 2SWP*MOV66B. In addition, the date for Corrective Action 5 has been revised to April 30, 1998. Temporary modifications have been made to assure that adequate eight hour capacity lighting is installed in required locations, therefore, this delay poses no safety concern.

Very truly yours,

B. Ralph Sylvia
Chief Nuclear Officer

BRS/GJG/lmc
Attachment

xc: Mr. H. J. Miller, Regional Administrator, Region I
Mr. B. S. Norris, Senior Resident Inspector
Records Management

9711030221 971028
PDR ADOCK 05000410
S PDR