REGULATORY INFORMATION DISTRIBUTION SYSTEM (RIDS)

ACCESSION NBR:8505170383 DOC.DATE: 85/05/03 NOTARIZED: NO DOCKET #
FACIL:50-387 Susquehanna Steam Electric Station, Unit 1, Pennsylva 05000387
50-388 Susquehanna Steam Electric Station, Unit 2, Pennsylva 05000388
AUTH.NAME AUTHOR AFFILIATION
CURTIS,N.W. Pennsylvania Power & Light Co.
RECIP.NAME RECIPIENT AFFILIATION
DIGGS,R.M. License Fee Management Branch

SUBJECT: Forwards fee for NRC reviews of inservice insp plan for Unit 2,feedwater bypass leakage limits & instrumentation for detection of inadequate core cooling.

DISTRIBUTION CODE: M008D COPIES RECEIVED:LTR 1 ENCL 0 SIZE: 1
TITLE: License Fees

NOTES:1cy NMSS/FCAF/PM. LPDR 2cys Transcripts. 05000387
OL:07/17/82
1cy NMSS/FCAF/PM. LPDR 2cys Transcripts. 05000388
OL:03/23/84

	RECIPIENT ID CODE/NAME		COPIES LTTR	COPIES ENCL	RECIPIENT ID CODE/NAME		COPIES LTTR	COPIES ENCL
	NRR LB2 BC	04	1	1	CAMPAGNONE	01	1	1
INTERNAL:	ADM/LFMB	06	1	1	REG FILE	04	1	1
EXTERNAL:	LPDR	03	2	2	NRC PDR	02	1	1
NOTES:			3	3				

TOTAL NUMBER OF COPIES REQUIRED: LTTR 10 ENCL 10

PP&L Pennsylvania Power & Light Company
Two North Ninth Street • Allentown, PA 18101 • 215 / 770-5151

Norman W. Curtis
Vice President-Engineering & Construction-Nuclear
215/770-7501

MAY 3 1985

Ms. Reba M. Diggs
Facilities Program Coordinator
Licensing Fee Management Branch
Office of Administration
U.S. Nuclear Regulatory Commission
Washington, D.C. 20555

SUSQUEHANNA STEAM ELECTRIC STATION
NRC FEES FOR REVIEWS
ER 100450 FILE 841
PLA-2463

Docket Nos. 50-387
and 50-388

Dear Ms. Diggs

Enclosed is a check for $450 to cover the fee for the following NRC reviews:

1. In-service Inspection Plan for Susquehanna SES Unit 2.

2. Feedwater Bypass Leakage Limits.

3. Instrumentation for Detection of Inadequate Core Cooling.

If you have any questions, please contact me.

Very truly yours,

N. W. Curtis
Vice President-Engineering & Construction-Nuclear

Enclosure

cc: M. J. Campagnone NRC

M008
1/0

Rec'd w/check $450.00

579574