U. S. NUCLEAR REGULATORY COMMISSION

# LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

| LICENSE CODE | | LICENSE NUMBER | | LICENSE TYPE | | CAT | |
|---|---|---|---|---|---|---|---|
| I L D R S 3 | (2) | 0 0 - 0 0 0 0 0 - 0 0 | (3) | 4 1 1 1 1 | (4) | | (5) |

| REPORT SOURCE | | DOCKET NUMBER | | EVENT DATE | | REPORT DATE | |
|---|---|---|---|---|---|---|---|
| L | (6) | 0 5 0 0 0 2 4 9 | (7) | 1 1 2 2 7 8 | (8) | 1 2 0 8 7 8 | (9) |

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

While performing monthly Surv. DIS 1500-4 (Containment Spray Interlocks - ECCS) face plate on Yarway model 4418C was found broken and holding pointer in a fixed position above trip setpt. Sw. affected was LIS 263-73A (>/= 2/3 rd Core Height). Safety significance was minimal since containment cooling valve operability could still be accomplished at the discretion of the unit operator. No similar event of this nature has occurred previously.

| SYSTEM CODE | | CAUSE CODE | | CAUSE SUBCODE | | COMPONENT CODE | | COMP. SUBCODE | | VALVE SUBCODE | |
|---|---|---|---|---|---|---|---|---|---|---|---|
| I A | (11) | A | (12) | X | (13) | I N S T R U | (14) | I | (15) | Z | (16) |

(17) LER/RO REPORT NUMBER

| EVENT YEAR | | SEQUENTIAL REPORT NO. | | OCCURRENCE CODE | REPORT TYPE | | REVISION NO. |
|---|---|---|---|---|---|---|---|
| 7 8 | — | 0 5 6 | / | 0 3 | L | — | 0 |

| ACTION TAKEN | | FUTURE ACTION | | EFFECT ON PLANT | | SHUTDOWN METHOD | | HOURS | | ATTACHMENT SUBMITTED | | NPRD-4 FORM SUB. | | PRIME COMP. SUPPLIER | | COMPONENT MANUFACTURER | |
|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|---|
| A | (18) | Z | (19) | Z | (20) | Z | (21) | 0 0 0 0 | (22) | N | (23) | N | (24) | N | (25) | Y 0 1 0 | (26) |

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

Cause of broken face plate and lodged pointer remains unknown. Face plate repaired and Yarway sw. setpt.'s were tested (DIS 1500-4) and found within Tech. Spec. limits, Table 3.2.2. LIS 263-73 A & B will continue to be tested monthly to verify compliance with T.S. No further actions now required.

| FACILITY STATUS | | % POWER | | OTHER STATUS | | METHOD OF DISCOVERY | | DISCOVERY DESCRIPTION | |
|---|---|---|---|---|---|---|---|---|---|
| E | (28) | 0 6 7 | (29) | NA | (30) | B | (31) | Surveillance Testing | (32) |

| ACTIVITY RELEASED | CONTENT OF RELEASE | | AMOUNT OF ACTIVITY | | LOCATION OF RELEASE | |
|---|---|---|---|---|---|---|
| Z (33) | Z | (34) | NA | (35) | NA | (36) |

PERSONNEL EXPOSURES

| NUMBER | | TYPE | | DESCRIPTION | |
|---|---|---|---|---|---|
| 0 0 0 | (37) | Z | (38) | NA | (39) |

PERSONNEL INJURIES

| NUMBER | | DESCRIPTION | |
|---|---|---|---|
| 0 0 0 | (40) | NA | (41) |

LOSS OF OR DAMAGE TO FACILITY (43)

| TYPE | | DESCRIPTION |
|---|---|---|
| Z | (42) | NA |

PUBLICITY

| ISSUED | | DESCRIPTION | NRC USE ONLY |
|---|---|---|---|
| N | (44) | NA (45) | |

7812180148

NAME OF PREPARER Carl Lindberg PHONE: X-289