(7-77)

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 — LICENSEE CODE: I L D R S 2 (2) — LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) — LICENSE TYPE: 4 1 1 1 1 (4) — CAT (5)

CON'T 01 — REPORT SOURCE: L (6) — DOCKET NUMBER: 0 5 0 0 0 2 3 7 (7) — EVENT DATE: 0 4 2 4 7 9 (8) — REPORT DATE: 0 5 2 4 7 9 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While Unit 2 was shutdown for refueling, U2 D/G failed to start during normal surveil-
03 lance. When upper bendix gear did not engage. Subsequent starts were successful.
04 Since Unit 2 was shutdown, safety significance of this event is minimal. Recent
05 failure to start reported in RO #78-50, 79-14, 79-22/50-237. These failures appear
06 to have resulted from same cause.
07
08

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
E E (11)	A (12)	C (13)	M O T O R X (14)	X (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
7 9	—	0 2 4	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
B (18)	G (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	N (25)	I 0 7 5 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Air lines to upper air start motor were found to be reversed. Air start motor re-
11 placed and air lines be properly routed. Maintenance personnel were instructed of
12 error. Diagram of proper air line routing will be added to maintenance procedure for
13 air start motor replacement.
14

15 — FACILITY STATUS: H (28) — % POWER: 0 0 0 (29) — OTHER STATUS (30): N/A — METHOD OF DISCOVERY: B (31) — DISCOVERY DESCRIPTION (32): N/A

16 — ACTIVITY RELEASED: Z (33) — CONTENT OF RELEASE: Z (34) — AMOUNT OF ACTIVITY (35): N/A — LOCATION OF RELEASE (36): N/A

17 — PERSONNEL EXPOSURES — NUMBER: 0 0 0 (37) — TYPE: Z (38) — DESCRIPTION (39): N/A

18 — PERSONNEL INJURIES — NUMBER: 0 0 0 (40) — DESCRIPTION (41): N/A

7905300573

19 — LOSS OF OR DAMAGE TO FACILITY (43) — TYPE: Z (42) — DESCRIPTION: N/A

20 — PUBLICITY — ISSUED: N (44) — DESCRIPTION (45): N/A — NRC USE ONLY

NAME OF PREPARER: J. Chan — PHONE: X-265

GPO 917-926