NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 | LICENSEE CODE: I L D R S 3 (2) | LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) | LICENSE TYPE: 4 1 1 1 1 (4) | CAT (5)

CON'T 01 | REPORT SOURCE: L (6) | DOCKET NUMBER: 0 5 0 0 0 2 4 9 (7) | EVENT DATE: 0 3 0 1 8 0 (8) | REPORT DATE: 0 3 2 6 8 0 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 During unit 3 shutdown while performing SBLC relief valve setting test, relief valves
03 RV 1105A and B actuated at 1525 psig and 1520 psig respectively. Tech. Spec. 4.4.A.
04 2.b limit for SBLC is 1400-1490 psig. Safety significance is minimal since SBLC could
05 have performed its intended function. Similar event: 50-237/76-27
06
07
08

09 | SYSTEM CODE: S H (11) | CAUSE CODE: E (12) | CAUSE SUBCODE: B (13) | COMPONENT CODE: V A L V E X (14) | COMP. SUBCODE: X (15) | VALVE SUBCODE: B (16)

(17) LER/RO REPORT NUMBER | EVENT YEAR: 8 0 | — | SEQUENTIAL REPORT NO.: 0 1 0 | / | OCCURRENCE CODE: 0 3 | REPORT TYPE: L | — | REVISION NO.: 0

ACTION TAKEN: E (18) | FUTURE ACTION: Z (19) | EFFECT ON PLANT: Z (20) | SHUTDOWN METHOD: Z (21) | HOURS (22): 0 0 0 0 | ATTACHMENT SUBMITTED: N (23) | NPRD-4 FORM SUB.: Y (24) | PRIME COMP. SUPPLIER: N (25) | COMPONENT MANUFACTURER: C 7 1 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 Change in relief valve setpoint was due to setpoint drift. Valves are 1½" by 2" self-
11 actuated disc type, relief valves, manufactured by Crosby Valve and Gage Co. Relief
12 valves were readjusted to approximately 1475 psig and successfully popped 5 times in
13 succession. Relief valve settings will continue to be tested each refueling cycle.
14

15 | FACILITY STATUS: H (28) | % POWER: 0 0 0 (29) | OTHER STATUS (30): N/A | METHOD OF DISCOVERY: B (31) | DISCOVERY DESCRIPTION (32): Maintenance Procedure

16 | ACTIVITY RELEASED: Z (33) | CONTENT OF RELEASE: Z (34) | AMOUNT OF ACTIVITY (35): N/A | LOCATION OF RELEASE (36): N/A

17 | PERSONNEL EXPOSURES NUMBER: 0 0 0 (37) | TYPE: Z (38) | DESCRIPTION (39): N/A

18 | PERSONNEL INJURIES NUMBER: 0 0 0 (40) | DESCRIPTION (41): N/A

19 | LOSS OF OR DAMAGE TO FACILITY (43) TYPE: Z (42) | DESCRIPTION: N/A

20 | PUBLICITY ISSUED: N (44) | DESCRIPTION (45): N/A | NRC USE ONLY

8004020337

R. A. Magron

X-526