NRC FORM 366 (7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | LICENSEE CODE: I L D R S 3 (2) | LICENSE NUMBER: 0 0 - 0 0 0 0 0 - 0 0 (3) | LICENSE TYPE: 4 1 1 1 1 (4) | CAT: (5)

CON'T 0 1 | REPORT SOURCE: L (6) | DOCKET NUMBER: 0 5 0 0 0 2 4 9 (7) | EVENT DATE: 0 6 2 0 8 0 (8) | REPORT DATE: 0 7 0 9 8 0 (9)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation it was noticed that an abnormal amount of water was being
0 3 added to the torus. Tests showed 3A LPCI Hx stayed pressurized on the tube side
0 4 when vented. (T.S. 6.6.B.2.d) this allowed LPCI water to enter the service water
0 5 side during idle conditions. It was immediately isolated. There was no danger to
0 6 the general public since redundant subsystem was available, and release was less than
0 7 100 pc/L Tech. Specs. limit. Similar occurrences: 50-237/77-20, 77-56, and 78-25.
0 8

SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
S F (11)	E (12)	C (13)	H T E X C H (14)	C (15)	Z (16)

(17) LER/RO REPORT NUMBER

EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
8 0	—	0 2 6	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
X (18)	X (19)	Z (20)	Z (21)	0 0 0 0	N (23)	Y (24)	N (25)	P 1 6 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Hydro of service water side indicated thirteen (13) tubes were leaking.
1 1 The tubes were subsequently plugged. Corrective actions are still being reviewed.
1 2
1 3
1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	E (28)	0 9 8 (29)	N/A	C (31)	Decreasing Level in Torus

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	L (33)	M (34)	.0982c	Reactor Building to Service Water

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	N/A

PUBLICITY

	ISSUED	DESCRIPTION (45)
2 0	N (44)	N/A

8007220459

NRC USE ONLY