NRC FORM 366
(7-77)

U.S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: | | | | | | | (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

0 1 | I L D R S 2 (2) | 0 0 - 0 0 0 0 0 - 0 0 (3) | 4 1 1 1 1 (4) | | (5)

LICENSEE CODE (9–14) · LICENSE NUMBER (15–25) · LICENSE TYPE (26–30) · CAT (57–58)

CON'T 0 1 REPORT SOURCE | L (6) | 0 5 0 0 0 2 3 7 (7) | 0 7 2 8 8 0 (8) | 0 8 1 8 8 0 (9)

DOCKET NUMBER (61–68) · EVENT DATE (69–74) · REPORT DATE (75–80)

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

0 2 During normal operation, while conducting routine inspection, water was found leaking

0 3 from weld on an instrument line off Rx. water cleanup sys. main header. Event was of

0 4 minimal safety significance because all leakage contained within Rx Bldg. Floor Drain

0 5 Sys. and Cleanup Sys. was capable of being isolated if required. Similar events

0 6 occurring previously at Dresden are: 78-046/03L-0 and 79-016/01T-0.

0 7

0 8

	SYSTEM CODE	CAUSE CODE	CAUSE SUBCODE	COMPONENT CODE	COMP. SUBCODE	VALVE SUBCODE
0 9	C G (11)	A (12)	E (13)	P I P E X X (14)	A (15)	Z (16)

(17) LER/RO REPORT NUMBER	EVENT YEAR		SEQUENTIAL REPORT NO.		OCCURRENCE CODE	REPORT TYPE		REVISION NO.
	8 0	—	0 2 9	/	0 3	L	—	0

ACTION TAKEN	FUTURE ACTION	EFFECT ON PLANT	SHUTDOWN METHOD	HOURS (22)	ATTACHMENT SUBMITTED	NPRD-4 FORM SUB.	PRIME COMP. SUPPLIER	COMPONENT MANUFACTURER
B (18)	Z (19)	Z (20)	Z (21)	0 0 0 0	N (23)	N (24)	N (25)	G 0 8 0 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

1 0 Probable cause was thermal cracking due to insufficient clearance on socket weld. Weld

1 1 was partially ground out, rewelded and dye penetrant tested satisfactorily. Weld to be

1 2 ground out and rewelded during the next refueling outage.

1 3

1 4

	FACILITY STATUS	% POWER	OTHER STATUS (30)	METHOD OF DISCOVERY	DISCOVERY DESCRIPTION (32)
1 5	G (28)	0 0 0 (29)	N/A	A (31)	Operator Observation

	ACTIVITY RELEASED	CONTENT OF RELEASE	AMOUNT OF ACTIVITY (35)	LOCATION OF RELEASE (36)
1 6	Z (33)	Z (34)	N/A	N/A

PERSONNEL EXPOSURES

	NUMBER	TYPE	DESCRIPTION (39)
1 7	0 0 0 (37)	Z (38)	N/A

PERSONNEL INJURIES

	NUMBER	DESCRIPTION (41)
1 8	0 0 0 (40)	N/A

LOSS OF OR DAMAGE TO FACILITY (43)

	TYPE	DESCRIPTION
1 9	Z (42)	N/A

PUBLICITY

	ISSUED	DESCRIPTION (45)	NRC USE ONLY
2 0	N (44)	N/A	

8009020388

NAME OF PREPARER S. A. Cieszkiewicz PHONE: X(815)942-2920 X-489

GPO 917-926