western union

Telegram

VEA509(2320)(1-03272303)PD 11/06/72 1923
ICS IPMVEIC MVN
ZCZC 00289 TDVE MORRIS ILL 114 11-06 346P CST
PMS MR BOYCE GRIER DIRECTOR DIVN OF COMPLIANCE
US ATOMIC ENERGY COMMISSION REGION 3
799 ROOSEVELT ROAD
GLEN ELLYN ILL 60137

1972 NOV 6 PM 10 41

TELEGRAMS (OTHER THAN MONEY ORDERS)
Special delivery requested? ____ (YES-AGENT, NO-ADDRESSEE)
AGENT SECTION
Nbr. & Name
Date did
Time did
To be mailed or delivered
Accepts to deliver (Indicate DA or BY)
ADDRESSEE SECTION
Nbr. 312-858-2660
To
By

SUBJECT: DPR-25 DRESDEN NUCLEAR POWER STATION UNIT 3.
THIS WILL CONFIRM A CONVERSATION WITH MR H BLANCE OF
YOUR OFFICE AT 1430 HOURS THIS DATE CONCERNING HPCI SYSTEM
INOPERABILITY. AT 0240 NOVEMBER 6 1972, WHILE CONDUCTIN
POST MAINTENANCE SURVEILLANCE DURING UNIT START-UP, THE
HPCI STEAM VALVE 2-2301-4 IN THE DRY WELL WOULD NOT
OPEN. ALTHOUGH THE STARTUP AND HEAT-UP WERE HALTED AT THIS
TIME, THE REACTOR PRESSURE DRIFTED UP TO ABOUT 100
LBS DURING INVESTIAGION OF THE VALVE PROBLEM. AT 0330, THE

NOV 1972

SF-1201 (R5-69)

Unit 2
HCD
11/10/72

SHIFT BEGAN A SHUT-DOWN OF THE UNIT. AT 0405, WITH REACTOR
PRESSURE 77PSIG AND SUB-CRITICAL, VALVE TESTED SATISFACTORILY.
AT0415 RESUMED START-UP. SATISFACTORILY TESTED HPCI
AT 0730 AT MINIMUM STEAM PRESSURE OF 110 PSI
W P WORDEN SUPERINTENDENT DRESDEN NUCLEAR POWER STATION
COMMONWEALTH EDISON RURAL ROUTE 1 MORRIS ILLINOIS

SF-1201 (R5-69)

147