NOTICE OF VIOLATION

Commonwealth Edison Company
Post Office Box 767
Chicago, IL 60690

Docket Nos. 50 237; 50-249

As a result of the inspection conducted on February 5 through March 9, 1990, and in accordance with the "general Statement of Policy and Procedure for NRC Enforcement Actions, " 10 CFR Part 2, Appendix C (1989) (Enforcement Policy), the following violation was identified:

10 CFR Part 50, Appendix B, Criterion V states in part, that activities affecting quality shall be prescribed by documented instructions, procedures, or drawings, and shall be accomplished in accordance with these instructions, procedures, or drawings.

Contrary to the above, during the performance of the Integrated Leak Rate Test on February 3 and 4, 1990, the licensee placed the containment isolation valves for the service air system in their test position without use of a procedure or instruction.

This is a Severity Level IV Violation (Supplement I).

Pursuant to the provision of 10 CFR 2.201, you are required to submit to this office within thirty days of the date of this Notice a written reply, including: (1) the corrective steps that have been taken and the results achieved; (2) the corrective steps that will be taken to avoid further violations; and (3) the date when full compliance will be achieved. Consideration may be given to extending your response time for good cause shown.

Dated

Geoffrey C. Wright, Chief
Operations Branch

9004290050 900330
PDR ADOCK 05000237
Q PDC