NRC FORM 366
(7-77)

U. S. NUCLEAR REGULATORY COMMISSION

LICENSEE EVENT REPORT

CONTROL BLOCK: (1) (PLEASE PRINT OR TYPE ALL REQUIRED INFORMATION)

01 FLSL S1 (2) 00-00 00 00 -00 (3) 4 1 1 1 1 (4) (5)
LICENSEE CODE — LICENSE NUMBER — LICENSE TYPE — CAT

CON'T
01 REPORT SOURCE L (6) 05 00 013 315 (7) 017 05 79 (8) 018 06 79 (9)
DOCKET NUMBER — EVENT DATE — REPORT DATE

EVENT DESCRIPTION AND PROBABLE CONSEQUENCES (10)

02 While reducing power for secondary system maintenance, CEA #62 slipped
03 from 134" to 120". Action in accordance with Tech. Spec 3.1.3.1.d (<15"
04 misalignment) was initiated. While trying to recover, CEA #62 slipped to
05 72" and action per Tech. Spec. 3.1.3.1.e (>15" misalignment) was initiated.
06 The timer module was replaced and CEA #62 was realigned within the time
07 limit specified. No power distribution limits were exceeded. This was
08 the third occurrence for CEA #62 (See LER's 335-78-43 and 335-79-10).

09 SYSTEM CODE RB (11) CAUSE CODE E (12) CAUSE SUBCODE A (13) COMPONENT CODE INSTRU (14) COMP. SUBCODE X (15) VALVE SUBCODE Z (16)

(17) LER/RO REPORT NUMBER: EVENT YEAR 79 — SEQUENTIAL REPORT NO. 024 — OCCURRENCE CODE 03 — REPORT TYPE L — REVISION NO. 0

ACTION TAKEN A (18) FUTURE ACTION Z (19) EFFECT ON PLANT Z (20) SHUTDOWN METHOD Z (21) HOURS (22) 0000 ATTACHMENT SUBMITTED N (23) NPRD-4 FORM SUB. N (24) PRIME COMP. SUPPLIER N (25) COMPONENT MANUFACTURER E146 (26)

CAUSE DESCRIPTION AND CORRECTIVE ACTIONS (27)

10 CEA #62 slipped due to a faulty timer module. No cause for the timer
11 module failure has been determined. The timer module was replaced and
12 CEA #62 performed normally. No other corrective action is required.
13 Power was reduced to 70% per Tech. Spec. 3.1.3.1.e. No power reduction is
14 attributed to this event since reduction was underway for maintenance.

15 FACILITY STATUS F (28) % POWER 100 (29) OTHER STATUS (30) NA METHOD OF DISCOVERY A (31) DISCOVERY DESCRIPTION (32) OPERATOR OBSERVATION

ACTIVITY RELEASED Z (33) CONTENT OF RELEASE Z (34) AMOUNT OF ACTIVITY (35) NA LOCATION OF RELEASE (36) NA

16 PERSONNEL EXPOSURES NUMBER 000 (37) TYPE Z (38) DESCRIPTION (39) NA

17 PERSONNEL INJURIES NUMBER 000 (40) DESCRIPTION (41) NA

18 LOSS OF OR DAMAGE TO FACILITY TYPE Z (42) DESCRIPTION (43) NA

19 PUBLICITY ISSUED N (44) DESCRIPTION (45) NA NRC USE ONLY

NAME OF PREPARER M. A. Schoppman PHONE: (305) 552-3802

7908200344