P.O. BOX 529100, MIAMI, FL 33152

FPL
FLORIDA POWER & LIGHT COMPANY

ACCELERATED DISTRIBUTION SERVICES UNIT
1981 JAN 2 PM 3 34
US NRC DISTRIBUTION SERVICES BRANCH

December 5, 1980

PRN-LI-80-514

Mr. James P. O'Reilly, Director, Region II
Office of Inspection and Enforcement
U.S. Nuclear Regulatory Commission
101 Marietta Street, Suite 3100
Atlanta, Georgia 30303

Dear Mr. O'Reilly:

REPORTABLE OCCURRENCE 335-80-63
ST. LUCIE UNIT 1
DATE OF OCCURRENCE: NOVEMBER 7, 1980

TECHNICAL SPECIFICATION 3.3.1.1

"C" PRESSURIZER PRESSURE CHANNEL

The attached Licensee Event Report is being submitted in accordance with Technical Specification 6.9 to provide 30 day notification of the subject occurrence.

Very truly yours,

A.D. Schmidt
Vice President
Power Resources

PLP/md

Attachment

cc: Director, Office of Inspection and Enforcement (30)
Harold F. Reis, Esquire
File

A002
S
1/1

8101050444
S